



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK CLK200 KOMPRESSOR ELEGANCE
Colour	Silver
Year of manufacture	2004
Top speed	139 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	42.2 mpg
Consumption combined	31.7 mpg
CO2 emission	221 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-11
Pictures	33
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-23
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	22
Total items failed	10

MOT #21	2023-08-24 15:32
MOT test number	411348736454
Result	✓ Passed
Next expiry date	2024-08-23

MOT #20	2023-08-23 10:24
MOT test number	147936936475
Result	✗ Failed
Fail	Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #19	2022-08-19 14:18
MOT test number	132092002634
Result	✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	O/s handbrake effort low

**MOT #18**

2021-09-22 09:50

MOT test number

712474843109

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement tie bar (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement tie bar (5.3.4 (a) (i))

MOT #17

2021-09-21 11:13

MOT test number

610755551164

Result

✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement tie bar (5.3.4 (a) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement tie bar (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #16

2020-09-11 11:13

MOT test number

125670556548

Result

✓ Passed

MOT #15

2019-06-07 13:38

MOT test number

231836143098

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2018-05-18 15:01**MOT test number** 170230719404**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front tyres perished**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #13** 2017-06-16 13:02**MOT test number** 865174069659**Result** ✓ Passed**MOT #12** 2016-06-15 12:43**MOT test number** 523734679523**Result** ✓ Passed**MOT #11** 2016-06-15 08:43**MOT test number** 875888744889**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Nail in tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-10-23 09:31**MOT test number** 955928358574**Result** ✓ Passed**Advice** Both rear tyres nearing limit

**MOT #9** 2014-10-16 14:00**MOT test number** 647179784254**Result** ✓ Passed**MOT #8** 2013-10-25 14:07**MOT test number** 845178093287**Result** ✓ Passed**MOT #7** 2013-10-25 14:07**MOT test number** 386188493286**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #6** 2012-10-25 10:32**MOT test number** 717319192215**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-10-24 10:28**MOT test number** 238377191267**Result** ✓ Passed**MOT #4** 2010-10-26 11:44**MOT test number** 320089490254**Result** ✓ Passed**Notice** Power steering pump very noisy

**MOT #3** 2010-10-25 09:52**MOT test number** 474168690238**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Power steering pump very noisy**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Notice** Puncture in N/S/R tyre**MOT #2** 2008-10-21 10:00**MOT test number** 582565198263**Result** ✓ Passed**Notice** Advise exhaust centre "y" piece joint fractured**MOT #1** 2007-10-23 17:44**MOT test number** 570446997274**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history


For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-28
Current registration	 XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-11-02
Last registration	2023-08-24
Complete history	See info



Registration #1	2004-11-02	26 mi
Registration #2	2007-10-23	46.778 mi
Registration #3	2008-10-21	52.566 mi
Registration #4	2010-10-25	59.849 mi
Registration #5	2010-10-26	59.850 mi
Registration #6	2011-10-24	61.768 mi
Registration #7	2012-10-25	64.381 mi
Registration #8	2013-10-25	65.959 mi
Registration #9	2014-10-16	67.859 mi
Registration #10	2015-10-23	69.717 mi
Registration #11	2016-06-15	70.288 mi
Registration #12	2016-06-15	70.288 mi
Registration #13	2016-06-15	70.288 mi
Registration #14	2016-06-15	70.288 mi
Registration #15	2016-06-15	70.288 mi
Registration #16	2016-06-15	70.288 mi
Registration #17	2016-06-15	70.288 mi
Registration #18	2016-06-15	70.288 mi
Registration #19	2016-06-15	70.288 mi
Registration #20	2016-06-15	70.288 mi
Registration #21	2016-06-15	70.288 mi
Registration #22	2016-06-15	70.288 mi

More info >



Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4643 mm
Wheel base	2690 mm
Kerb weight	1665 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	27194030284185