



NJ09LDY


report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Red
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-17
Pictures	28
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-16
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	25
Total items failed	2

MOT #18	2023-08-17 13:42
MOT test number	596290883271
Result	✓ Passed
Next expiry date	2024-08-16

MOT #17	2023-08-11 14:46
MOT test number	603296208477
Result	✗ Failed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16	2022-05-11 12:30
MOT test number	830853902066
Result	✓ Passed
Advice	Oil leak, but not excessive drive shaft oil seals (8.4.1 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Central Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

**MOT #15** 2022-05-11 09:22**MOT test number** 194807403718**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Central Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Oil leak, but not excessive drive shaft oil seals (8.4.1 (a) (i))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #14** 2021-05-27 08:30**MOT test number** 963780531718**Result** ✓ Passed**MOT #13** 2021-01-22 11:49**MOT test number** 941650614417**Result** ✓ Passed**MOT #12** 2021-01-18 13:47**MOT test number** 188121407947**Result** ✗ Failed**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2020-01-23 11:32**MOT test number** 688472025518**Result** ✓ Passed**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10** 2020-01-22 12:30**MOT test number** 753714514384**Result** ✗ Failed**MAJOR** Boot lid damaged and likely to cause injury (6.2.1 (a) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Boot lid cannot be secured in the closed position (6.2.1 (e))**Minor** Rear Registration plate lamp throwing direct white light to the rear (4.7.1 (a))**MOT #9** 2019-01-17 11:27**MOT test number** 153317745048**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2018-01-23 11:24**MOT test number** 116712208941**Result** ✓ Passed**MOT #7** 2017-01-17 11:37**MOT test number** 592558164636**Result** ✓ Passed**MOT #6** 2016-01-19 13:40**MOT test number** 511802932005**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-01-10 11:06**MOT test number** 476980215004**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2014-01-14 13:26**MOT test number** 475154814032**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2013-01-25 12:03**MOT test number** 398265323058**Result** ✓ Passed**MOT #2** 2012-01-30 12:29**MOT test number** 226610232093**Result** ✓ Passed**MOT #1** 2012-01-30 12:29**MOT test number** 648680632043**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 August 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-24
Last registration	2023-08-17
Complete history	See info



Registration #1	2009-03-24	24 mi
Registration #2	2012-01-30	28.915 mi
Registration #3	2013-01-25	32.491 mi
Registration #4	2014-01-14	37.236 mi
Registration #5	2015-01-10	43.152 mi
Registration #6	2016-01-19	49.892 mi
Registration #7	2017-01-17	54.467 mi
Registration #8	2018-01-23	58.778 mi
Registration #9	2019-01-17	64.223 mi
Registration #10	2020-01-22	68.815 mi
Registration #11	2020-01-22	73.377 mi
Registration #12	2020-01-22	77.939 mi
Registration #13	2020-01-22	82.501 mi
Registration #14	2020-01-22	87.063 mi
Registration #15	2020-01-22	91.625 mi
Registration #16	2020-01-22	96.187 mi
Registration #17	2020-01-22	100.749 mi
Registration #18	2020-01-22	105.311 mi
Registration #19	2020-01-22	109.873 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0048476