



**SNI3ZZH**

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	UP UP BLACK
Colour	Red
Year of manufacture	2013
Top speed	106 mph
0 - 100 km/h	13.2 seconds
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 kW / 75 HP / 74 BHP
Max. torque	95 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-08-09
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-12
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	18
Total items failed	10

MOT #15	2023-07-24 11:34
MOT test number	223404139428
Result	✓ Passed
Next expiry date	2024-08-12
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-07-24 07:43
MOT test number	730964254521
Result	✗ Failed
Fail	Offside Rear Service brake lagging in operation (1.2.1 (d))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-07-18 08:18
MOT test number	926882652521
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing CRACKING (5.2.3 (d) (ii))

**MOT #12** 2022-07-18 08:18**MOT test number** 763391929519**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing CRACKING (5.2.3 (d) (ii))**MOT #11** 2021-08-13 13:43**MOT test number** 258240933455**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10** 2021-08-13 08:28**MOT test number** 674532115251**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**MOT #9** 2020-11-28 09:52**MOT test number** 407511493242**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases front pipe flexi (6.1.2 (a))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #8** 2019-11-27 12:57**MOT test number** 338480394860**Result** ✓ Passed**Advice** Hand brake lever travel**Advice** Exhaust box corroding**Advice** Engine oil low**MOT #7** 2019-11-27 11:59**MOT test number** 403306989655**Result** ✗ Failed**Advice** Engine oil low**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Hand brake lever travel**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Exhaust box corroding**MOT #6** 2018-11-30 12:45**MOT test number** 704540231419**Result** ✓ Passed**MOT #5** 2017-11-28 18:49**MOT test number** 930369388311**Result** ✓ Passed

**MOT #4** 2017-11-15 19:43**MOT test number** 870026754234**Result** ✗ Failed**Fail** Offside rear brake binding (3.7.B.1)**Advice** Front pads low**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2016-11-24 07:52**MOT test number** 625617834561**Result** ✓ Passed**MOT #2** 2015-12-02 17:14**MOT test number** 657464455909**Result** ✓ Passed**MOT #1** 2015-12-01 17:30**MOT test number** 992508577714**Result** ✗ Failed**Fail** Offside Front Front wheel bearing rough when rotated (2.5.A.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
12 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	12 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>SN13ZZH</b>
Plate since	2019-03-28
Current registration	<b>SN13ZZH</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-03-08
Last registration	2023-07-24
Complete history	<a href="#">See info</a>



Registration #1	2013-03-08	11 mi
Registration #2	2015-12-01	29.250 mi
Registration #3	2015-12-02	29.250 mi
Registration #4	2016-11-24	42.572 mi
Registration #5	2017-11-15	55.123 mi
Registration #6	2017-11-28	55.123 mi
Registration #7	2018-11-30	64.409 mi
Registration #8	2019-11-27	73.128 mi
Registration #9	2019-11-27	73.128 mi
Registration #10	2019-11-27	73.128 mi
Registration #11	2019-11-27	73.128 mi
Registration #12	2019-11-27	73.128 mi
Registration #13	2019-11-27	73.128 mi
Registration #14	2019-11-27	73.128 mi
Registration #15	2019-11-27	73.128 mi
Registration #16	2019-11-27	73.128 mi
Registration #17	2019-11-27	73.128 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	80%
Pedestrian	46%
Safety systems	86%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1645 mm
Height	1489 mm
Length	3540 mm
Wheel base	2420 mm
Kerb weight	829 kg
Max. allowed weight	1290 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of axles	2
Engine number	CHYB240539