



PJIOKAO


report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Brown
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-01-11
Pictures	38
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-13
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	38
Total items failed	22

MOT #20	2024-01-10 14:30
MOT test number	276359168524
Result	✓ Passed
Next expiry date	2025-01-13
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Outer Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Outer Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #19	2024-01-09 11:20
MOT test number	421380089269
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Outer Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Outer Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #18**

2023-01-11 15:41

MOT test number

335171831376

Result

✓ Passed

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Outer Integral body structure is corroded but structural rigidity is not significantly reduced Sill. (6.1.1 (c) (i))

MOT #17

2023-01-11 10:31

MOT test number

510278541142

Result

✗ Failed

- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))
- Advice** Nearside Front Outer Integral body structure is corroded but structural rigidity is not significantly reduced Sill. (6.1.1 (c) (i))

MOT #16

2022-01-14 11:12

MOT test number

775635094284

Result

✓ Passed

**MOT #15**

2021-11-25 15:20

MOT test number

211279678751

Result**✗ Failed**

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))

MOT #14

2020-12-05 14:24

MOT test number

569649492381

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Suspension rod ball joint has slight play (5.3.4 (a) (i))

MOT #13

2019-03-14 17:29

MOT test number

737725293087

Result**✓ Passed****MOT #12**

2019-03-14 11:45

MOT test number

946645634740

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-03-27 14:57**MOT test number** 926613381469**Result** ✓ Passed**Advice** Under trays fitted**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2018-03-26 11:51**MOT test number** 267943842218**Result** ✗ Failed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.A.3)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Advice** Under trays fitted**MOT #9** 2017-03-10 15:37**MOT test number** 195025673835**Result** ✓ Passed**Advice** Advise top + bottom engine covers fitted**Advice** Play in steering rack inner joint(s)

**MOT #8** 2017-03-06 14:13**MOT test number** 803945973424**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.A.3)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Advise top + bottom engine covers fitted**Advice** Play in steering rack inner joint(s)**MOT #7** 2016-03-11 11:43**MOT test number** 810967414022**Result** ✓ Passed**Advice** Advise rear brake pads low**Advice** Advise top + bottom engine covers fitted**Advice** Advise child seats fitted**MOT #6** 2016-03-11 11:43**MOT test number** 772949284099**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Advise rear brake pads low**Advice** Advise top + bottom engine covers fitted**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Advise child seats fitted

**MOT #5** 2015-02-25 12:56**MOT test number** 978176055077**Result** ✓ Passed**MOT #4** 2015-02-23 15:54**MOT test number** 195324655497**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #3** 2014-02-25 14:48**MOT test number** 396786154012**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2013-03-15 13:51**MOT test number** 725644173009**Result** ✓ Passed**MOT #1** 2013-03-15 13:51**MOT test number** 528944773014**Result** ✗ Failed**Pass with rectification** Nearside Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
13 January 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-04-24
Last registration	2024-01-10
Complete history	See info



Registration #1	2010-04-24	12 mi
Registration #2	2013-03-15	12.831 mi
Registration #3	2014-02-25	19.725 mi
Registration #4	2015-02-23	27.925 mi
Registration #5	2015-02-25	28.004 mi
Registration #6	2016-03-11	38.599 mi
Registration #7	2016-03-11	38.599 mi
Registration #8	2017-03-06	48.446 mi
Registration #9	2017-03-10	48.449 mi
Registration #10	2018-03-26	59.817 mi
Registration #11	2018-03-27	59.824 mi
Registration #12	2019-03-20	71.277 mi
Registration #13	2019-03-20	71.277 mi
Registration #14	2019-03-20	71.277 mi
Registration #15	2019-03-20	71.277 mi
Registration #16	2019-03-20	71.277 mi
Registration #17	2019-03-20	71.277 mi
Registration #18	2019-03-20	71.277 mi
Registration #19	2019-03-20	71.277 mi
Registration #20	2019-03-20	71.277 mi
Registration #21	2019-03-20	71.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0086665