





report date: 2024-03-29

General information

Make	FIAT
Model	TIPO EASY PLUS
Colour	Blue
Year of manufacture	2018
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-06-24

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-20
Pictures	15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-31
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #4	2024-03-27 15:31
MOT test number	355140253433
Result	✓ Passed
Next expiry date	2025-03-31
Advice TPMS light on	
Advice Front Anti-roll bar linkage ball joint has slight play o/s & n/s (5.3.4 (a) (i))
Minor Offside Rear reflector defective or damaged by up to 50% of the reflecti	ng surface (4.8.1 (a) (i))
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened slightly corroded on inner surface (1.1.14 (a) (ii))	
Minor Nearside Rear reflector defective or damaged by up to 50% of the reflective or damaged by up to 50% of the r	cting surface (4.8.1 (a) (i))

MOT #3	2023-03-30 1	1:19
MOT test	t number 699921365	161
Result	✓ Pas	ssed
Advice	Rear Tyre slightly damaged/cracking or perishing o/s & n/s outer sidewalls cracking (5.2.3 (d) (ii	i))
Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))		1)

CarCheck.co.uk page 3/11



Advice

PK18OHT

report date: 2024-03-29

MOT test number

Result

Advice
Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice
Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice
Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1	2021-03-27 10:10
MOT test number	721623098556
Result	✓ Passed

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



PK18OHT report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-29
Last registration	2024-03-27
Complete history	See info



Registration #1	2018-03-29	25 mi
Registration #2	2021-03-27	12.302 mi
Registration #3		11.777 mi
Registration #4		0.00 44
Registration #5		11.777 mi
Registration #6		11.777 es
Registration #7		11.777 no

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles2Engine number4122426