



General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Silver
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D





## MOT history

MOT expiry date	2024-06-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	33
Total items failed	7

MOT #16	2023-06-22 15:26
MOT test number	929444298526
Result	✓ Passed
Next expiry date	2024-06-21
Advice	O/s/f seat belt slow to retract
Advice	Offside Rear Tyre worn close to legal limit/worn on edge also out of shape inner edge (5.2.3 (e))

MOT #15	2022-03-15 12:47
MOT test number	451547279213
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing slight out of shape on inner edge (5.2.3 (d) (ii))

MOT #14	2021-04-12 12:02
MOT test number	749404550394
Result	✓ Passed

MOT #13	2020-03-16 14:56
MOT test number	825042343755
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2019-03-13 08:18

**MOT test number**

266760737318

**Result**

✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #11**

2019-03-06 10:43

**MOT test number**

152173373156

**Result**

✓ Passed

**Advice** Long travel park brake**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #10**

2019-03-05 16:15

**MOT test number**

901672853489

**Result**

✗ Failed

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Long travel park brake**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #9**

2018-03-05 12:29

**MOT test number**

592007039359

**Result**

✓ Passed

**Advice**

Long travel park brake

**MOT #8**

2017-03-02 13:29

**MOT test number**

232236458452

**Result**

✓ Passed

**Advice**

Park brake just met minimum required effort

**Advice**

Long travel park brake

**Advice**

Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7**

2017-03-02 13:29

**MOT test number**

500168822129

**Result**

✗ Failed

**Advice**

Park brake just met minimum required effort

**Advice**

Front Brake pad(s) wearing thin (3.5.1g)

**Advice**

Long travel park brake

**Pass with rectification**

Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #6**

2016-03-01 14:33

**MOT test number**

391599707958

**Result**

✓ Passed

**Advice**

Nearside Front Tyre low depth on inner edge

**Advice**

Offside Rear Tyre low depth on outer edge

**Advice**

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Offside Front Tyre low depth on inner edge

**MOT #5** 2016-03-01 14:33**MOT test number** 366876142553**Result** ✗ Failed**Pass with rectification** Nearside Front Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Tyre low depth on inner edge**Advice** Offside Rear Tyre low depth on outer edge**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre low depth on inner edge**MOT #4** 2015-02-23 14:38**MOT test number** 268014355053**Result** ✓ Passed**Notice** Rear tyres badly perished**MOT #3** 2015-02-23 14:38**MOT test number** 366424255081**Result** ✗ Failed**Notice** Rear tyres badly perished**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2014-02-22 10:56**MOT test number** 789783354024**Result** ✓ Passed**MOT #1** 2013-03-16 11:14**MOT test number** 826445173004**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>WN10CWT</b>
Plate since	2019-06-29
Current registration	 <b>WN10CWT</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-31
Last registration	2023-06-22
Complete history	<a href="#">See info</a>



Registration #1	2010-03-31	27 mi
Registration #2	2013-03-16	18.179 mi
Registration #3	2014-02-22	22.670 mi
Registration #4	2015-02-23	26.463 mi
Registration #5	2016-03-01	29.219 mi
Registration #6	2016-03-01	29.219 mi
Registration #7	2017-03-02	32.911 mi
Registration #8	2017-03-02	32.911 mi
Registration #9	2018-03-01	35.577 mi
Registration #10	2018-03-01	35.577 mi
Registration #11	2019-03-01	38.243 mi
Registration #12	2019-03-01	38.243 mi
Registration #13	2020-03-01	40.909 mi
Registration #14	2020-03-01	40.909 mi
Registration #15	2021-03-01	43.575 mi
Registration #16	2023-06-22	46.241 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843