





report date: 2024-03-29

#### General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Red
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2025-03-28
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	3

MOT #9	2024-03-13 10:40
MOT test number	732690599716
Result	✓ Passed
Next expiry date	2025-03-28
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (2	1.1.11 (c))

MOT #8		2023-03-15 09:38
MOT test	number	158810127634
Result		✓ Passed
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		(c))
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice	Oil leak, but not excessive sump pan leaking (8.4.1 (a) (i))	

MOT #7	2022-03-29 17:17
MOT test number	222073634911
Result	<b>✓</b> Passed

CarCheck.co.uk page 2/11



**Advice** 

YY13WFT report date: 2024-03-29

MOT test number

401645390437

Result

Fail Nearside Headlamp insecure (4.1.1 (c))

Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))

MOT #5

MOT test number

Result

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

 MOT #4
 2019-05-14 13:35

 MOT test number
 739242523359

 Result
 ✓ Passed

MOT #3

MOT test number

821081929534

Result

✓ Passed

MOT #2

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 3/11



**MOT #1** 2016-06-01 07:59

**MOT test number** 757944413189

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside rear and offside rear tyres slightly mishaped inner tread..

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	28 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STATE OF THE S	
***************************************	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	SK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-06-08
Last registration	2024-03-13
Complete history	See info



Registration #1	2013-06-08	7 mi
Registration #2	2016-06-01	21.084 mi
Registration #3	2017-05-30	28.658 mi
Registration #4	2018-05-14	36.716 mi
Registration #5	2019-05-14	42.083 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 es
		11.777 es 11.777 es
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11



## Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number U054847