





report date: 2024-03-29

## General information

Make	FORD
Model	RANGER DCB XLT 4X4
Colour	Silver
Year of manufacture	2007
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	140 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

## Entry 1

Date 2021-07-17


Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



GU57LDV report date: 2024-03-29

**MOT** history

MOT expiry date	2024-01-31
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	27
Total items failed	15

MOT #21	2023-02-01 11:37
MOT test number	968859814022
Result	<b>✓</b> Passed
Next expiry date	2024-01-31
Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working C (4.3.1 (a) (ii))  Advice Rear Rear axle diff housing leaking oil	Centre high level brake light inop

MOT #20	2022-01-25 09:52
MOT test number	391634228006
Result	<b>✓</b> Passed

MOT #19	2022-01-19 15:28
MOT test number	767973682414
Result	<b>X</b> Failed
Fail Rear Registration plate lamp inoperative in the case of a single lamp of	or all lamps (4.7.1 (b) (ii))

Fail Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))

Fail Front Steering component mounting prescribed area is excessively corroded cross member (2.1.2 (e) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice Front steering has slight movement

Advice Front Oil leak, but not excessive diff (8.4.1 (a) (i))

Advice Rear Oil leak, but not excessive diff (8.4.1 (a) (i))

**MOT #17** 2021-04-22 16:13 **MOT** test number 227640125537 Result × Failed Fail Rear Brake pipe excessively corroded 3 pipes on load sensors (1.1.11 (c)) Advice Front steering has slight movement Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Front Oil leak, but not excessive diff (8.4.1 (a) (i)) Advice Front front panel slight corrosion Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Rear Oil leak, but not excessive diff (8.4.1 (a) (i))

 MOT #16
 2020-07-01 17:53

 MOT test number
 269856953317

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #15
 2019-08-21 11:49

 MOT test number
 916094911596

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



GU57LDV report date: 2024-03-29

**MOT #14** 2018-09-04 10:25

MOT test number 632024062243

**Result** ✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #13** 2017-09-05 10:21

MOT test number 696284401699

Result \sqrt{ Passed

**Advice** Offside Brake pipe slightly corroded front to rear pipe above gearbox crossmember (3.6.B.2c)

**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1a)

MOT #12 2017-09-05 10:21

MOT test number 206594769352

Result X Failed

**Advice** Offside Brake pipe slightly corroded front to rear pipe above gearbox crossmember (3.6.B.2c)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1a)

**MOT #11** 2016-09-09 07:59

MOT test number 585148987999

Result 

Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #10 2015-09-07 14:12

**MOT test number** 277728684258

**Result** ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #9 2014-09-02 17:52

**MOT test number** 416905244212

MOT #8 2014-09-01 17:01

MOT test number 339984644260

Result X Failed

**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)

**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)

MOT #7 2013-08-28 14:21

**MOT test number** 167860543239

Result \rightarrow Passed

MOT #6 2012-08-20 14:19

MOT test number 337913932220

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2012-08-20 14:19

MOT test number 439013332295

Result X Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 6/13



report date: 2024-03-29

**MOT #4** 2011-09-06 17:29

**MOT test number** 315799041201

**Result** ✓ Passed

MOT #3 2011-09-05 15:42

**MOT test number** 538158641298

Result X Failed

Fail Brakes imbalanced across an axle (3.7.B.5b)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2010-09-03 08:45

**MOT test number** 334826440219

Result \( \sqrt{Passed} \)

**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-09-03 08:45

**MOT test number** 771276740223

**Result** X Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/13



GU57LDV report date: 2024-03-29

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	hictor,
UWNEI	nisioiv
OWINCE	THISCOLY

e when miscory		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
**************************************		
***************************************		
*********		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	OK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



**GU57LDV** report date: 2024-03-29

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-06
Last registration	2023-02-01
Complete history	See info



Registration #1	2007-09-06	6 mi
Registration #2	2010-09-03	65.169 mi
Registration #3	2011-09-05	84.059 mi
Registration #4	2011-09-06	84.062 mi
Registration #5	2012-08-20	92.863 mi
Registration #6	2013-08-28	99.948 mi
Registration #7	2014-09-01	107.314 mi
Registration #8	2014-09-02	107.314 mi
Registration #9	2015-09-07	115.237 mi
Registration #10	2016-09-09	124.784 mi
Registration #11	2017-09-05	131.362 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		9.700 esi
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 12/13



GU57LDV report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	718492

CarCheck.co.uk page 13/13