



TOYOTA

ND6INUM


report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Silver
Year of manufacture	2011
Top speed	93 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2023-03-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 1

Date	2021-12-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-03-01
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	18
Total items failed	4

MOT #14	2024-02-08 11:27
MOT test number	402894710171
Result	✓ Passed
Next expiry date	2025-03-01

MOT #13	2023-03-01 14:55
MOT test number	304054402914
Result	✓ Passed
Advice	Rear Brake pipe corroded, covered in grease or other material both rear pipes grease (1.1.11 (c))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened rear disc corroded (1.1.14 (a) (ii))

MOT #12	2023-02-28 13:44
MOT test number	977501349689
Result	✗ Failed
Advice	Nearside Front pad rattle
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened rear disc corroded (1.1.14 (a) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Brake pipe corroded, covered in grease or other material both rear pipes grease (1.1.11 (c))

**MOT #11** 2022-02-09 13:39**MOT test number** 179669953784**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material COATED IN GREASE (1.1.11 (c))**MOT #10** 2021-08-18 10:28**MOT test number** 882522879733**Result** ✓ Passed**MOT #9** 2020-07-29 15:46**MOT test number** 635334794334**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material To caliper (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material To caliper (1.1.11 (c))**MOT #8** 2020-07-29 10:54**MOT test number** 483669675132**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material To caliper (1.1.11 (c))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material To caliper (1.1.11 (c))**MOT #7** 2019-08-01 10:25**MOT test number** 373274507974**Result** ✓ Passed

**MOT #6** 2018-08-07 16:38**MOT test number** 737916782226**Result** ✓ Passed**MOT #5** 2018-08-06 16:20**MOT test number** 196115810862**Result** ✗ Failed**Advice** Offside Front tyre signs of cracking ( sidewall)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front tyre signs of cracking( sidewall)**Advice** Offside Rear tyre signs of cracking**MOT #4** 2017-08-14 13:59**MOT test number** 487567644328**Result** ✓ Passed**MOT #3** 2016-08-23 10:51**MOT test number** 375994824412**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear coil spring corroded n/s and o/s (2.4.C.1b)**Advice** Rear n/s and o/s tyres cracks in treads**MOT #2** 2015-09-16 09:32**MOT test number** 438513295420**Result** ✓ Passed



MOT #1	2014-10-13 12:14
MOT test number	285596884283
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>ND61NUM</b>
Plate since	2024-03-28
Current registration	<b>ND61NUM</b>
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-12-20
Last registration	2024-02-08
Complete history	<a href="#">See info</a>



Registration #1	2011-12-20	13 mi
Registration #2	2014-10-13	33.793 mi
Registration #3	2015-09-16	34.157 mi
Registration #4	2016-08-23	36.423 mi
Registration #5	2017-08-14	42.037 mi
Registration #6	2018-08-06	43.234 mi
Registration #7	2018-08-07	43.235 mi
Registration #8	2019-08-01	44.323 mi
Registration #9	2020-07-29	45.253 mi
Registration #10	2020-08-01	45.253 mi
Registration #11	2020-08-01	45.253 mi
Registration #12	2020-08-01	45.253 mi
Registration #13	2020-08-01	45.253 mi
Registration #14	2020-08-01	45.253 mi
Registration #15	2020-08-01	45.253 mi
Registration #16	2020-08-01	45.253 mi
Registration #17	2020-08-01	45.253 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1KR1188526