





report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history


Entry 1


Date 2021-12-12

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT #22	2021-01-16 09:01
MOT test number	415106050846
Result	✓ Passed

Next expiry date 2022-02-06

MOT #21 2021-01-16 09:01

MOT test number 346530862715

Result X Failed

Pass with rectification Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii))

Pass with rectification Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii))

Pass with rectification Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

 MOT #20
 2020-01-22 11:50

 MOT test number
 877021804623

 Result
 Passed

MOT #19 2020-01-22 11:50

MOT test number 478318016659

Result × Failed

Pass with rectificationNearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18 2019-02-07 17:33

MOT test number 721025619869

Advice Offside Rear tyre perrishing

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #17	2019-02-07 12:01
MOT test	number 769289868766
Result	★ Failed
MAJOR	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b)
Advice	Offside Rear tyre perrishing
MAJOR	Front Service brake excessively binding (1.2.1 (f))
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #16		2018-04-17 12:47
MOT test	number	362541004861
Result		✓ Passed
Advice	Rear axle corroded	
Advice	Offside Rear tyre perishing	
Advice	Nearside Front seat belt locking mechanism cove damaged	
Advice	Nearside Front brakes slightly binding	
Advice	Nearside Rear wheel bearing slightly noisy	

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #15 2018-04-17 08:52 310723773326 **MOT** test number Result × Failed **Advice** Nearside Front brakes slightly binding Advice Nearside Rear wheel bearing slightly noisy Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3) Fail Offside Rear Rear wheel bearing rough when rotated (2.6.1) Rear axle corroded Advice Advice Offside Rear tyre perishing Advice Nearside Front seat belt locking mechanism cove damaged Fail Offside Registration plate lamp not working (1.1.C.1d) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #14	2017-04-06 12:24
MOT test number	888199816204
Result	✓ Passed
MOT #13	2017-04-06 07:43
MOT test number	106388030449

MOT #	13	2017-04-06 07:43
MOT te	st number	106388030449
Result		X Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Fail	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Fail	Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #12 2016-04-16 11:09 **MOT** test number 555496457327 Result ✓ Passed **MOT #11** 2016-04-12 08:25 **MOT** test number 343856004865 Result × Failed **Advice** Nearside Front Tyre worn close to the legal limit 2mm and inner edge worn (4.1.E.1) Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f) **Advice** Play in steering inner joints **Advice** Offside Front Tyre worn close to the legal limit 2mm and inner edge worn (4.1.E.1)

MOT #10

MOT test number

Result

Notice Unable to see inner pads

Notice Nsr tyre perishing

Notice Play in steering rack inner joint(s)

Notice Nail in nearside rear tyre

 MOT #9
 2014-04-05 09:39

 MOT test number
 467395594002

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #8		2013-03-23 09:30
MOT test	number	328162283029
Result		✓ Passed
Notice	Fuel tank strap heavily corroded	
Notice	Exhaust rear silencer heavily corroded	

MOT #7		2012-03-30 15:11
MOT test number		158660992073
Result		✓ Passed
MOT #6		2011-04-02 09:39
MOT test number		168312091065
Result		✓ Passed
MOT #5		2010-03-27 09:37
MOT test number		482706480098
Result		✓ Passed
MOT #4		2010-03-27 09:37
MOT test number		743666880055
Result		X Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #3	2009-04-04 10:27
MOT test number	774134199094
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 7/14



report date: 2024-03-28

MOT #2 2008-04-16 15:26 **MOT test number** 243967108468 ✓ Passed Result MOT #1 2008-04-10 13:14 923891708100 **MOT test number X** Failed Result Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

Sime misery	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

THE STREET STREE	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIX
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-04-20
Last registration	2021-01-16
Complete history	See info



Registration #1	2005-04-20	17 mi
Registration #2	2008-04-10	23.121 mi
Registration #3	2008-04-16	23.185 mi
Registration #4	2009-04-04	26.994 mi
Registration #5	2010-03-27	30.868 mi
Registration #6	2011-04-02	35.594 mi
Registration #7	2012-03-30	39.856 mi
Registration #8	2013-03-23	45.759 mi
Registration #9	2014-04-05	52.895 mi
Registration #10	2015-03-27	58.667 mi
Registration #11	2016-04-12	63.559 mi
Registration #12	2016-04-16	63.559 mi
Registration #13		11.777 es
Registration #14		11.177 ea
Registration #15		
Registration #16		0.074
Registration #16 Registration #17		11.777 es
-		11.777 es 11.777 es 11.777 es
Registration #17		11.777 es 11.777 es 11.777 es 11.777 es
Registration #17 Registration #18		11.777 es 11.777 es 11.777 es 11.777 es
Registration #17 Registration #18 Registration #19		11.777 est 11.777 est 11.777 est 11.777 est 11.777 est
Registration #17 Registration #18 Registration #19 Registration #20		11 777 46 11 777 46 11 777 46 11 777 46 11 777 46

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/

Number of axles 2

Engine number FSR95191649