





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 ACTIVE
Colour	White
Year of manufacture	2014
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



WK64XUX report date: 2024-03-29

Internet history

	-	4.	M3 /	- 1
ᆮ	п	ш	ľV	- 1

ciitiy 1	
Date	2021-03-04
Pictures	0
Listing price	View report

source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2024-07-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	3
Total items failed	9

MOT #9	2023-07-18 14:04
MOT test number	395532435458
Result	✓ Passed
Next expiry date	2024-07-17

MOT #8	2022-05-17 16:46
MOT test number	972439042482
Result	✓ Passed

MOT #	<i>I</i>	2022-05-17 14:23
MOT te	est number	643729302529
Result		X Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #6	2021-04-13 15:43
MOT test number	599572306408
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2020-09-28 08:12

MOT test number 483505921630

Result \(\sqrt{Passed} \)

MOT #4 2019-10-02 15:34

MOT test number 247277690118

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2018-11-17 10:58

MOT test number 536960237814

Result \(\sqrt{Passed} \)

MOT #2 2017-11-14 16:00

MOT test number 287499203408

MOT #1 2017-09-06 12:39

MOT test number 534244591157

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Front brake application uneven (3.7.B.2)

Fail Rear parking (secondary) brakes imbalanced (3.7.B.6b)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Rear brake application uneven (3.7.B.2)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

WK64XUX

report date: 2024-03-29

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info

Plate changes

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-29
Last registration	2023-07-18
Complete history	See info



Registration #1	2014-10-29	16 mi
Registration #2	2017-09-06	34.430 mi
Registration #3	2017-11-14	34.436 mi
Registration #4	2018-11-17	40.564 mi
Registration #5	2019-10-02	44.446 mi
Registration #6	2020-09-28	48.746 mi
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 10/11




WK64XUX report date: 2024-03-29

Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number G4LADM174143