





### General information

Make	MERCEDES
Model	CL 500 500
Colour	Black
Year of manufacture	2008
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	7 speed automatic

### Engine & fuel consumption

Power	382 BHP
Max. torque	530 Nm at 2.800 rpm
Engine capacity	5.462 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.6 mpg
Consumption extra urban	33.2 mpg
Consumption combined	23.3 mpg
CO2 emission	288 g/km
CO2 label	Μ







## Internet history

Entry 2

Date Pictures 2022-04-06

12

Listing price

View report



source: cargurus.co.uk

Entry 1	
Date	2021-12-24
Pictures	29
Listing price	<u>View report</u>



source: autotrader.co.uk









## MOT history

MOT expiry date	2024-09-13
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	13
Total items failed	4

MOT #13		2023-09-06 09:46
MOT test number	r	754178330286
Result		✓ Passed
Next expiry date 2024-09-		2024-09-13
<b>Advice</b> Offside	e Front Lower Macpherson strut ball joint has slight play (5.3.4 (a)	(i))
Advice Offside	e Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #12		2022-09-07 08:14
MOT test	number	418034055310
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2021-09-14 15:45
MOT test number	819537176311
Result	✓ Passed





MOT #10	2020-08-24 15:54
MOT test number	945770687450
Result	✓ Passed
МОТ #9	2019-08-22 09:25
MOT test number	901069587331
Result	✓ Passed

MOT #8		2018-08-09 13:49
MOT test	number	452262171963
Result		✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #7	2017-08-24 16:47
MOT test number	594517874679
Result	✓ Passed

МОТ #6	2017-08-24 08:31
MOT test number	309050081622
Result	🗙 Failed
<b>Fail</b> Rear registration plate has a feature which changes the appearance or legibilit (6.3.4c)	y of the characters
<b>Fail</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
<b>Fail</b> Front registration plate has a feature which changes the appearance or legibilit (6.3.4c)	ty of the characters
<b>Fail</b> Nearside Front Tyre has a bulge, caused by separation or partial failure of its st (4.1.D.1b)	tructure outer side wall
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #5	2016-08-26 15:50
MOT test number	438051892466
Result	✓ Passed
MOT #4	2015-08-24 11:39
MOT test number	675349527170
Result	✓ Passed

MOT #3		2014-03-04 10:35
MOT test	number	495703164098
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2012-12-20 16:45
MOT test number	906085952396
Result	✓ Passed
MOT #1	2012-01-13 11:27
MOT test number	768153112073
Result	✓ Passed



## Tax & MOT check

✓ Taxed	✓ MOT
<b>Tax due:</b> 1 April 2025	<b>Expires:</b> 13 September 2024
Tax status	Valid until 1 April
Days left	337
MOT expiry date	13 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	AMP
Туре	A CONTRACT
Damage 2	AMPLE
Damaye z	E CAT D
Date	
Category	AMPT
Туре	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
********	
	More info >
Plate changes See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-12-30
Last registration	2023-09-06
Complete history	See info



Registration #1	2008-12-30	12 mi
Registration #2	2012-01-13	42.141 mi
Registration #3	2012-12-20	44.834 mi
Registration #4	2014-03-04	54.161 mi
Registration #5	2015-08-24	65.656 mi
Registration #6	2016-08-26	76.116 mi
Registration #7	2017-08-24	87.901 mi
Registration #8	2017-08-24	87.903 mi
- <b>J</b>		
Registration #9		11.777 esi
		10.000 est
Registration #9		01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11		01.000 est 01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1871 mm
Height	1418 mm
Length	5065 mm
Wheel base	2955 mm
Kerb weight	1995 kg
Additional information	
Fuel tank capacity	90
Fuel tank capacity Fuel delivery	90 l Multi-Point Injection
Fuel delivery	Multi-Point Injection
Fuel delivery Number of doors	Multi-Point Injection