



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER DCLL 35 DCI 100 DCB
Colour	Red
Year of manufacture	2005
Top speed	81 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	260 Nm at 1.500 rpm
Engine capacity	2.463 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-11
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2022-11-24
<b>MOT pass rate</b>	67 %
<b>MOT passed</b>	14
<b>Failed MOT tests</b>	7
<b>Total advice items</b>	71
<b>Total items failed</b>	23

**MOT #21** 2021-11-25 08:47**MOT test number** 640068871594**Result** Passed**Next expiry date** 2022-11-24

- Advice** Nearside Front seat fixing missing but security and function not affected
- Advice** Front Registration plate deteriorated but not likely to be misread slightly damaged (0.1 (b))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #20** 2020-10-27 16:55**MOT test number** 525088310006**Result** Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #19**

2020-10-24 11:20

**MOT test number**

760342522724

**Result**

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #18**

2019-10-30 15:07

**MOT test number**

286441069695

**Result**

✓ Passed

- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear brake pipes very rusty x 2 (1.1.11 (c))
- Advice** Offside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity lens cracked (4.2.3 (b) (ii))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement bush perished (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive major engine oil leak coating lower engine and o/s front suspension (but no dripping to the road) (8.4.1 (a) (i))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced chassis ladder and outriggers have surface rust (6.1.1 (c) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread cracked/damaged (0.1 (b))
- Advice** Front Bumper mountings corroded but not likely to become detached mountings and clips missing and damaged (6.1.4 (a) (i))
- Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement inner wishbone bushies perished (5.3.4 (a) (i))

**MOT #17**

2019-10-23 09:53

**MOT test number**

513127658039

**Result****✗ Failed**

**Advice** Offside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity lens cracked (4.2.3 (b) (ii))

**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear brake pipes very rusty x 2 (1.1.11 (c))

**Fail** Offside Front Headlamp aim too high (4.1.2 (a))

**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement bush perished (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive major engine oil leak coating lower engine and o/s front suspension (but no dripping to the road) (8.4.1 (a) (i))

**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))

**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))

**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced chassis ladder and outriggers have surface rust (6.1.1 (c) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread cracked/damaged (0.1 (b))

**Advice** Front Bumper mountings corroded but not likely to become detached mountings and clips missing and damaged (6.1.4 (a) (i))

**Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement inner wishbone bushies perished (5.3.4 (a) (i))

**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #16	2018-10-25 11:30
MOT test number	846536703615
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Oil leak

MOT #15	2017-10-06 10:46
MOT test number	281839767988
Result	✓ Passed
Advice	Oil leak

**MOT #14**

2017-10-03 09:53

**MOT test number**

881083881016

**Result****✗ Failed**

- Advice** Front slight damage to number plate
- Advice** Oil leak heavy contamination
- Advice** Nearside slight body damage to sliding door (no sharp edges)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside slight scratching on windscreen (not affecting drivers view of road)
- Advice** Nearside Front slight damage to front door exterior plastic trip (no sharp edges)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Brake pipe slightly corroded various location on front to rear pipes (3.6.B.2c)
- Advice** Headlamp mask converters fitted

**MOT #13**

2016-09-28 12:23

**MOT test number**

902430663850

**Result****✓ Passed**

- Advice** Oil leak

**MOT #12**

2016-09-28 09:47

**MOT test number**

216876402806

**Result****✗ Failed**

- Advice** Oil leak
- Fail** Centre Stop lamp not working (1.2.1b)



MOT #11	2015-10-21 12:42
MOT test number	203321901197
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10	2014-09-19 15:05
MOT test number	516572664226
Result	✓ Passed
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Notice	Oil leak
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Notice	Coolant leak





MOT #9 2014-09-16 10:23

MOT test number 397859754223

Result ✗ Failed

- Notice** Coolant leak
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Offside Rear rear brake excessively fluctuating (3.7.B.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Oil leak
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Service brake: efficiency below requirements (3.7.B.7)
- Advice** Offside Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #8 2013-08-28 14:39

MOT test number 837950043296

Result ✓ Passed

**MOT #7** 2012-09-06 15:58**MOT test number** 266700852259**Result** ✓ Passed**Notice** Oil leak**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #6** 2011-08-30 16:13**MOT test number** 975622741218**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #5** 2010-09-07 11:35**MOT test number** 273390050250**Result** ✓ Passed**Advice** Offside Rear rear brake grabbing slightly (3.7.A.5b)**MOT #4** 2010-09-06 10:48**MOT test number** 122499140202**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** N/s/r lens damaged (non obligatory fog lamp showing white light to rear when operated)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside rear brake binding (3.7.B.1)**MOT #3** 2009-09-07 16:57**MOT test number** 174440759212**Result** ✓ Passed



MOT #2	2008-09-09 11:05
MOT test number	501923558239
Result	✓ Passed

MOT #1	2008-09-02 12:23
MOT test number	694606448232
Result	✗ Failed
<div><div>Fail</div>Power steering component(s) leaking (2.3.3b)</div> <div><div>Fail</div>Centre Stop lamp emits other than a steady red light (1.2.1e)</div> <div><div>Fail</div>Nearside Steering rack gaiter split (2.2.D.2d)</div>	



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 April 2022

✕  
MOT

Expired:  
24 November 2022

Tax status

Expired at 1 April 2022

Days left

760 days too late

MOT expiry date

24 November 2022

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 NL55YXS
Plate since	2019-03-29
Current registration	 NL55YXS
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-08
Last registration	2021-11-25
Complete history	<a href="#">See info</a>



Registration #1	2005-09-08	23 mi
Registration #2	2008-09-02	47.393 mi
Registration #3	2008-09-09	47.393 mi
Registration #4	2009-09-07	58.619 mi
Registration #5	2010-09-06	71.962 mi
Registration #6	2010-09-07	71.981 mi
Registration #7	2011-08-30	95.254 mi
Registration #8	2012-09-06	100.480 mi
Registration #9	2013-08-28	115.077 mi
Registration #10	2014-09-16	131.308 mi
Registration #11	2014-09-19	131.311 mi
Registration #12	2015-10-21	140.566 mi
Registration #13	2016-09-02	151.277 mi
Registration #14	2016-09-02	151.277 mi
Registration #15	2016-09-02	151.277 mi
Registration #16	2016-09-02	151.277 mi
Registration #17	2016-09-02	151.277 mi
Registration #18	2016-09-02	151.277 mi
Registration #19	2016-09-02	151.277 mi
Registration #20	2016-09-02	151.277 mi
Registration #21	2016-09-02	151.277 mi
Registration #22	2016-09-02	151.277 mi
Registration #23	2016-09-02	151.277 mi

More info >





Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2359 mm
Height	2200 mm
Length	6330 mm
Kerb weight	1814 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	7
Engine number	C101877