



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Black
Year of manufacture	2015
Top speed	104 mph
0 - 60 mph	13.5 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-11-10
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-02
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	17
Total items failed	7

MOT #8	2024-04-03 15:17
MOT test number	816140815426
Result	✓ Passed
Next expiry date	2025-04-02
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear brake binding
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	TPMS light on

**MOT #7**

2024-04-02 16:48

**MOT test number**

724084091630

**Result****✗ Failed**

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear brake binding
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** TPMS light on
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6**

2023-03-08 16:01

**MOT test number**

973494485997

**Result****✓ Passed**

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #5**

2021-12-07 15:31

**MOT test number**

975364627373

**Result****✓ Passed**



MOT #4	2021-06-10 10:20
MOT test number	960760859497
Result	✓ Passed
Advice	Play in steering rack inner joint(s)
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Oil low (service lamp on)

MOT #3	2020-06-15 14:29
MOT test number	854503013207
Result	✓ Passed

MOT #2	2019-06-20 10:02
MOT test number	308717507606
Result	✓ Passed

MOT #1	2018-06-01 13:07
MOT test number	402944580646
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
2 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	2 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>EU15UHF</b>
Plate since	2024-03-29
Current registration	 <b>EU15UHF</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-06-22
Last registration	2024-04-03
Complete history	<a href="#">See info</a>



Registration #1	2015-06-22	12 mi
Registration #2	2018-06-01	82.305 mi
Registration #3	2019-06-20	94.929 mi
Registration #4	2020-06-15	102.465 mi
Registration #5	2021-06-10	108.039 mi
Registration #6	2022-06-20	115.277 mi
Registration #7	2023-06-20	121.277 mi
Registration #8	2024-06-20	127.277 mi
Registration #9	2025-06-20	133.277 mi
Registration #10	2026-06-20	139.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2062 mm
Height	1856 mm
Length	4406 mm
Kerb weight	1496 kg
Max. allowed weight	2280 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2

**Engine number**

CAYDBG1624