





report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B170 SE
Colour	Silver
Year of manufacture	2006
Top speed	112 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.699 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	171 g/km
CO2 label	Н



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-24
Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-02
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	22
Total items failed	7

MOT #20		2023-07-03 09:03
MOT test	number	805700249834
Result		✓ Passed
Next expiry date 2024-07-02		
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely de	eteriorated (6.1.7 (g) (i))

MOT #19	2022-06-06 16:09
MOT test	number 751246128358
Result	✓ Passed
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18		2021-05-27 11:03
MOT test i	number	557376569535
Result		✓ Passed
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #17 2021-05-24 16:55

MOT test number 557791863393

Result X Failed

Fail Offside Front Windscreen washer not working (3.5 (a))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #16 2020-06-19 11:03

MOT test number 422895116169

Result \square Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #15 2019-06-27 15:09

MOT test number 941987689559

Advice Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

MOT #14 2018-06-27 13:36

MOT test number 716267831502

Result

Passed

Advice All tyres starting to perish

Advice Rear Tyre worn close to legal limit/worn on edge inner edge on both sides (5.2.3 (e))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #13

MOT test number

Result

Advice
Both rear tyres are perished

Advice
Both front brake discs are slightly worn

MOT #12

MOT test number

578865281064

Result

Advice Both Front brake discs are slightly worn

MOT #11

MOT test number

239830085433

Result

Notice Engine sounds very tappity when running

MOT #10

MOT test number

Result

Pass with rectification

Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

Notice

Engine sounds very tappity when running

MOT test number

Result

Advice

Rear Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)

Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

CarCheck.co.uk page 5/14



Pass with rectification

LX560EM

report date: 2024-03-29

MOT test number

168664174274

Result

Pass with rectification

Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice

Rear Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)

Pass with rectification

Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT test number

Result

MOT test number

Result

MOT #6

2013-09-30 15:23

MOT test number

569853573209

Result

Pass with rectification

Offside Front constant velocity joint is insecure (2.5.C.1b)

 MOT #5
 2012-10-03 15:17

 MOT test number
 437437772217

 Result
 ✓ Passed

 MOT #4
 2012-10-03 15:17

 MOT test number
 238127472235

 Result
 X Failed

 MOT #3
 2011-09-08 12:51

 MOT test number
 867291351220

 Result
 ✓ Passed

Nearside Headlamp aim too low (1.8)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2	2010-08-26 10:42
MOT test number	421038430274
Result	✓ Passed
MOT #1	2009-09-10 11:23
MOT test number	443603959283
Result	✓ Passed

CarCheck.co.uk page 7/14



LX560EM report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



LX560EM report date: 2024-03-29

Owner history

Owner matery	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-21
Last registration	2023-07-03
Complete history	See info



Registration #1	2006-09-21	11 mi
Registration #2	2009-09-10	24.785 mi
Registration #3	2010-08-26	35.660 mi
Registration #4	2011-09-08	44.964 mi
Registration #5	2012-10-03	52.417 mi
Registration #6	2013-09-30	59.999 mi
Registration #7	2014-10-01	66.879 mi
Registration #8	2015-06-29	70.756 mi
Registration #9	2016-06-22	77.405 mi
negistration #5		
Registration #10	mm-n-n	11.77 46
	2003-29-29	11,177 ea 11,177 ea
Registration #10	2000-20-20 2000-20-20 2000-20-20	11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11	100-10-10 100-10-10 100-10-10	11.777 es 11.777 es 11.777 es
Registration #10 Registration #11 Registration #12	100-10-10 100-10-10 100-10-10	11.77 es 11.77 es 11.77 es
Registration #10 Registration #11 Registration #12 Registration #13	100-10-10 100-10-10 100-10-10 100-10-10	11.77 es 11.77 es 11.77 es 11.77 es
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14	100-10-10 100-10-10 100-10-10 100-10-10 100-10-10	11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	900-0-0 900-0-0 900-0-0 900-0-0 900-0-0	11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 13/14



LX560EM report date: 2024-03-29

Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1310 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	54 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26694030256373

CarCheck.co.uk page 14/14