





report date: 2024-03-29

### General information

Make	FORD
Model	FOCUS RS
Colour	White
Year of manufacture	2010
Top speed	163 mph
0 - 60 mph	5.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	300 BHP
Max. torque	440 Nm at 2.300 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	30.1 mpg
CO2 emission	225 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

#### Entry 2

Date 2023-03-29

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-01-30	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history
-------------

MOT expiry date	2025-01-15
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #12	2024-01-16 11:56
MOT test number	407211370672
Result	✓ Passed
Next expiry date	2025-01-15

MOT #11	2021-08-06 08:34
MOT test number	566923798740
Result	<b>✓</b> Passed

MOT #10	2020-06-19 08:43
MOT test number	503903882770
Result	<b>✓</b> Passed

**MOT test number** 691741000718

Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)
Advice	Nearside Front Tyre slightly damaged and slight bulge on side wall (5.2.3 (d) (ii))	
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Oil leak, but not excessive from nearside drive shaft oil seal (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



Result

Result

**EN10AVO** report date: 2024-03-29

× Failed

**MOT** #8 2018-05-22 11:35

**MOT** test number 947421771950

Passed

Minor Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Nearside Rear Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))

Oil leak, but not excessive (8.4.1 (a) (i)) Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i)) Advice

Advice Offside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i)) **Advice** 

**MOT #7** 2018-05-22 11:10

393805673730 **MOT** test number

**Advice** Offside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Nearside Rear Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i)) Advice

**Advice** Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Minor Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Horn not working (7.7 (a) (ii)) Fail

Advice Nearside Front Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))

CarCheck.co.uk page 4/13



**EN10AVO** 

report date: 2024-03-29

MOT #6		2017-05-22 10:05
MOT test	number	486650282546
Result		✓ Passed
Advice	Under trays fitted	
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		sive movement
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in exce	essive movement

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement		
(2.4.G.2)		
MOT #5		2016-06-01 13:34
MOT test number		566929263860
Result		✓ Passed
MOT #4		2015-11-13 08:29
MOT test number		484065830451
Result		✓ Passed
MOT #3		2015-11-13 08:29
MOT test number		783669934490
Result		<b>X</b> Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)	
Pass with rectification	Nearside Front Headlamp aim too low (1.8)	

MOT #2		2014-11-17 17:00
MOT test	number	575291324334
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Items removed from driver's view prior to test	

CarCheck.co.uk page 5/13



MOT #1 2013-08-30 10:58

**MOT test number** 347622243481

CarCheck.co.uk page 6/13



#### Tax & MOT check

Tax expired: 12 August 2021



Expires: 15 January 2025

✓ MOT

Tax status	Expired at 12 August 2021
Days left	991 days too late
MOT expiry date	15 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



**EN10AVO** 

report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e mier metery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-30
Last registration	2024-01-16
Complete history	See info



Registration #1	2010-06-30	8 mi
Registration #2	2013-08-30	16.935 mi
Registration #3	2014-11-17	20.942 mi
Registration #4	2015-11-13	21.383 mi
Registration #5	2015-11-13	21.383 mi
Registration #6	2016-06-01	21.735 mi
Registration #7	2017-05-22	28.267 mi
Registration #8	2018-05-22	33.372 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.177 ms

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1842 mm
Height	1484 mm
Length	4402 mm
Wheel base	2640 mm
Kerb weight	1479 kg
Max. allowed weight	1860 kg

## Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles2Engine numberAS12813