






General information

Make	ΤΟΥΟΤΑ
Model	PRIUS VVT-I T SPIRIT
Colour	Blue
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	10.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	70.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	89 g/km
CO2 label	A





MOT history

MOT expiry date	2021-08-12
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	2

MOT #13		2020-08-13 15:16
MOT test	number	247992604746
Result		✓ Passed
Next expi	ry date	2021-08-12
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Steering column deformed but serviceable (2.1.3 (c) (i))	

MOT #12	20	19-10-23 08:05
MOT test	number	834725206003
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.	14 (a) (ii))
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #11		2019-04-23 13:35
MOT test i	number	230166091080
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both si	ides (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2018-10-24 13:02
MOT test I	umber 134418781890
Result	✓ Passed
Advice (ii))	Front Brake disc worn, pitted or scored, but not seriously weakened both sides lipped (1.1.14 (a)

МОТ #9	2018-04-30 13:01
MOT test number	840836490985
Result	✓ Passed

MOT #8		2018-04-30 13:01
MOT test number		145020123628
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (1.7.5a)	

MOT #7	2017-10-31 11:31
MOT test number	583040917852
Result	✓ Passed

MOT #6		2017-10-31 11:31
MOT test number		938200415428
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (1.7.5a)	





MOT #5	2017-05-04 15:58
MOT test number	355392860106
Result	✓ Passed
МОТ #4	2016-06-13 12:22
MOT test number	314546777303
Result	✓ Passed
MOT #3	2015-06-15 10:34
MOT test number	305636165184
Result	✓ Passed
MOT #2	2014-06-16 12:00
MOT test number	739737164111
Result	✓ Passed

Juic		V Tusseu
Notice	Stone chip to swept area of windscreen	
Notice	Handbrake travel long	
	Notice	Notice Stone chip to swept area of windscreen

MOT #1		2013-06-26 11:03
MOT test	number	557667273125
Result		✓ Passed
Advice requires a	Parking brake: parking brake efficiency only just met. It would appear that th djustment or repair. (3.7.B.7)	e braking system
Notice	Handbrake on travel limits	
Notice	N/s/r brake noisey when turned (squeal shim?)	
Notice	Chip zone 'b' of windscreen	
Notice	Rear discs very poor condition	
Notice	O/s wiper blade poor	



KN10XKD report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 3 February 2021	X MOT Expired: 12 August 2021
Tax status	Expired at 3 February 2021
Days left	1181 days too late
MOT expiry date	12 August 2021
Full MOT history	See MOT history
Tax calculation	
Vehicle class	59
Band	А
Single payment (12 months)	£ 0,00,-

Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.200
Auction value	4 10.000
Average private trade value	4 11 200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Current registration Plate since	ж uk





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



KN10XKD report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-06-24
Last registration	2020-08-13
Complete history	See info



Registration #1	2010-06-24	22 mi
Registration #2	2013-06-26	56.032 mi
Registration #3	2014-06-16	64.161 mi
Registration #4	2015-06-15	72.760 mi
Registration #5	2016-06-13	81.129 mi
Registration #6	2017-05-04	88.718 mi
Registration #7	2017-10-31	112.413 mi
Registration #8		10.000 mil
Registration #0		
Registration #9		11.277 mi
-		10.000 est
Registration #9		01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		10.000 est 10.000 est 10.000 est 10.000 est
Registration #9 Registration #10 Registration #11		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	82%
Pedestrian	68%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1745 mm
Height	1490 mm
Length	4460 mm
Wheel base	2700 mm
Kerb weight	1420 kg
Max. allowed weight	1805 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11