



PEUGEOT

KN60LU0

report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 HDI SPORT
Colour	Grey
Year of manufacture	-
Top speed	114 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg





Internet history

Entry 1

Date	2021-06-06
Pictures	27
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #17** 2023-01-09 15:52**MOT test number** 414719587624**Result** ✓ Passed**Next expiry date** 2024-01-10**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16** 2023-01-09 09:49**MOT test number** 869929632370**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**MOT #15** 2022-01-06 11:51**MOT test number** 156970312332**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-01-06 11:51**MOT test number** 183474300028**Result** ✗ Failed**Pass with rectification** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2021-01-11 12:14**MOT test number** 761965109211**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-01-11 10:49**MOT test number** 964264269420**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Power steering component insecure rack boot (2.1.5 (d) (i))**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Power steering component insecure rack boot (2.1.5 (d) (i))**Fail** Front Oil leaking excessively from engine (8.4.1 (a) (i))**MOT #11** 2020-01-06 13:07**MOT test number** 943387697602**Result** ✓ Passed

**MOT #10** 2020-01-06 10:58**MOT test number** 783588114124**Result** ✗ Failed**Fail** Rear Exhaust system insecure (6.1.2 (a))**Fail** Offside Front Power steering component insecure and steering adversely affected rack boot insecure (2.1.5 (d) (ii))**MOT #9** 2019-01-04 10:30**MOT test number** 404129317216**Result** ✓ Passed**MOT #8** 2017-12-07 15:19**MOT test number** 406452814132**Result** ✓ Passed**Advice** Oil leak**MOT #7** 2017-12-06 09:30**MOT test number** 593863340504**Result** ✗ Failed**Fail** Electronic power steering warning lamp indicates a failure in the system (2.3.8)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Oil leak**Fail** Power steering inoperative (2.3.3a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-12-12 16:47**MOT test number** 652009215240**Result** ✓ Passed**Advice** Front brake disc inner faces corroded

**MOT #5** 2016-12-12 13:19**MOT test number** 918223895342**Result** ✗ Failed**Advice** Front brake disc inner faces corroded**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #4** 2015-12-30 12:53**MOT test number** 475402414401**Result** ✓ Passed**Advice** Front brake discs corroded slightly**Advice** Nearside front wheel rim bent slightly**MOT #3** 2015-01-05 09:25**MOT test number** 105245605495**Result** ✓ Passed**MOT #2** 2013-09-18 15:27**MOT test number** 139851863237**Result** ✓ Passed**Notice** Rear exhaust hanger broken but exhaust still supported.**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Slight oil leak at engine**Notice** Slight leak present at additive container.



MOT #12013-09-18 10:08

MOT test number295661163209

ResultX Failed

AdviceFront registration plate deteriorated but not likely to be misread (6.3.1d)

NoticeSlight oil leak at engine

NoticeSlight leak present at additive container.

FailOffside Front Windscreen washer provides insufficient washer liquid (8.2.3)

NoticeRear exhaust hanger broken but exhaust still supported.

FailNearside Front Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KN60LUO
Plate since	2019-03-29
Current registration	KN60LUO
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-30
Last registration	2023-01-09
Complete history	See info



Registration #1	2010-09-30	20 mi
Registration #2	2013-09-18	37.928 mi
Registration #3	2013-09-18	37.928 mi
Registration #4	2015-01-05	53.658 mi
Registration #5	2015-12-30	60.721 mi
Registration #6	2016-12-12	69.103 mi
Registration #7	2016-12-12	69.103 mi
Registration #8	2017-12-06	78.438 mi
Registration #9	2017-12-07	78.450 mi
Registration #10	2019-01-04	84.435 mi
Registration #11	2019-01-04	84.435 mi
Registration #12	2019-01-04	84.435 mi
Registration #13	2019-01-04	84.435 mi
Registration #14	2019-01-04	84.435 mi
Registration #15	2019-01-04	84.435 mi
Registration #16	2019-01-04	84.435 mi
Registration #17	2019-01-04	84.435 mi
Registration #18	2019-01-04	84.435 mi
Registration #19	2019-01-04	84.435 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1277 kg
Max. allowed weight	1718 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBCL3051640