



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 SWB VAN 104TDI
Colour	White
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel






Internet history

Entry 1

Date	2021-06-23
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-07
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	17
Total items failed	6

MOT #13	2024-03-08 14:00
MOT test number	878771632498
Result	✓ Passed
Next expiry date	2025-03-07
Advice	Nearside Front Outer cv boot weeping
Advice	Oil stains on engine
Advice	Nearside Front slight damage

MOT #12	2023-03-03 13:49
MOT test number	340912699540
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust corroded and worn but not blowing
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Under body corrosion

**MOT #11**

2022-03-07 17:44

**MOT test number**

269195844190

**Result**

✓ Passed

- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Wheel bearing has slight play
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Exhaust back box corroded

**MOT #10**

2022-03-04 09:35

**MOT test number**

469707765874

**Result**

✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear exhaust casing cover insecure
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))
- Advice** Rear Shock absorbers has slight external damage to the casing both (5.3.2 (b))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #9**

2020-12-02 16:50

**MOT test number**

794173509436

**Result**

✓ Passed

**MOT #8**

2019-06-12 12:41

**MOT test number**

632426623150

**Result**

✓ Passed



<b>MOT #7</b>	2019-06-12 12:41
---------------	------------------

<b>MOT test number</b>	296181640845
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Nearside Front All position lamps not working (4.2.1 (a))
--------------------------------	-----------------------------------------------------------

<b>MOT #6</b>	2018-05-25 14:14
---------------	------------------

<b>MOT test number</b>	869839911781
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2017-05-12 15:49
---------------	------------------

<b>MOT test number</b>	299050551835
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2016-05-04 09:18
---------------	------------------

<b>MOT test number</b>	939297438134
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-04-17 11:18
---------------	------------------

<b>MOT test number</b>	275877605153
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Shock absorber has a light misting of oil (2.7.3)
---------------	------------------------------------------------------------------

<b>MOT #2</b>	2014-04-18 10:03
---------------	------------------

<b>MOT test number</b>	328618604114
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #1	2013-04-12 14:23
MOT test number	916652203134
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
7 March 2025

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	94
------------------	----

<b>MOT expiry date</b>	7 March 2025
------------------------	--------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>SD10EXP</b>
Plate since	2024-03-29
Current registration	 <b>SD10EXP</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-30
Last registration	2024-03-08
Complete history	<a href="#">See info</a>



Registration #1	2010-04-30	13 mi
Registration #2	2013-04-12	46.586 mi
Registration #3	2014-04-18	60.891 mi
Registration #4	2015-04-17	73.305 mi
Registration #5	2016-05-04	78.219 mi
Registration #6	2017-05-12	82.198 mi
Registration #7	2018-05-25	86.253 mi
Registration #8	2019-06-12	95.699 mi
Registration #9	2020-06-25	105.145 mi
Registration #10	2021-07-08	114.591 mi
Registration #11	2022-07-21	124.037 mi
Registration #12	2023-08-04	133.483 mi
Registration #13	2024-03-08	142.929 mi
Registration #14		
Registration #15		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width2062 mm

Length4405 mm

Additional information

Fuel tank capacity55 l

Fuel deliveryDirect Injection

Number of doors3

Number of seats2

Engine numberBLS C56612