



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	LUPO E
Colour	Silver
Year of manufacture	2004
Top speed	104 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-22
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	24
Total items failed	5

MOT #21	2024-02-20 10:55
MOT test number	485941522181
Result	✓ Passed
Next expiry date	2025-02-22

MOT #20	2023-02-14 11:37
MOT test number	361801450680
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #19	2022-01-26 15:33
MOT test number	708750794500
Result	✓ Passed
Minor	Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18	2022-01-26 15:33
MOT test number	856922417932
Result	✗ Failed
Minor	Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Pass with rectification	Horn not working (7.7 (a))

**MOT #17** 2021-01-26 15:46**MOT test number** 130022030450**Result** ✓ Passed**Advice** Front lower arm ball joint bush worn**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #16** 2020-02-11 11:47**MOT test number** 500810173193**Result** ✓ Passed**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**MOT #15** 2020-02-11 09:17**MOT test number** 402858170373**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**MOT #14** 2019-02-15 17:47**MOT test number** 261991562977**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Lower Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Swivel joint (2.1.3 (g) (i))**Minor** Nearside Front Lower Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Swivel joint (2.1.3 (g) (i))**Minor** Central Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #13** 2018-02-15 09:30**MOT test number** 912344941940**Result** ✓ Passed

Advice Supplementary Restraint System warning lamp does not illuminate think srs lamp has been covered by tape behind dash lens (5.4.2)

Advice Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #12 2017-02-22 15:32**MOT test number** 264521620291**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #11 2017-02-22 08:57**MOT test number** 561825698808**Result** ✗ Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

Fail Offside Rear Stop lamp not working (1.2.1b)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10 2016-02-15 12:19**MOT test number** 405953343729**Result** ✓ Passed**MOT #9** 2015-02-23 13:12**MOT test number** 506044255030**Result** ✓ Passed

**MOT #8** 2014-02-21 13:58**MOT test number** 698912654006**Result** ✓ Passed**MOT #7** 2013-02-22 10:12**MOT test number** 448423553040**Result** ✓ Passed**MOT #6** 2012-03-20 09:34**MOT test number** 568810582069**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #5** 2011-04-01 12:14**MOT test number** 858571091046**Result** ✓ Passed**MOT #4** 2009-03-30 10:55**MOT test number** 802259689001**Result** ✓ Passed**Notice** Slight scratch windscreen**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear number plate slight damage**MOT #3** 2008-03-31 10:59**MOT test number** 100531398040**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #2	2008-03-31 10:59
MOT test number	372431498050
Result	✓ Passed

MOT #1	2007-04-14 07:56
MOT test number	761004207142
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL04DVZ
Plate since	2024-03-29
Current registration	 GL04DVZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-04-25
Last registration	2024-02-20
Complete history	See info



Registration #1	2004-04-25	21 mi
Registration #2	2007-04-14	3.458 mi
Registration #3	2008-03-31	10.061 mi
Registration #4	2009-03-30	18.808 mi
Registration #5	2011-04-01	33.103 mi
Registration #6	2012-03-20	35.916 mi
Registration #7	2013-02-22	40.855 mi
Registration #8	2014-02-21	47.063 mi
Registration #9	2015-02-23	49.158 mi
Registration #10	2016-02-15	49.942 mi
Registration #11	2017-02-22	51.208 mi
Registration #12	2018-02-20	51.208 mi
Registration #13	2019-02-20	51.208 mi
Registration #14	2020-02-20	51.208 mi
Registration #15	2021-02-20	51.208 mi
Registration #16	2022-02-20	51.208 mi
Registration #17	2023-02-20	51.208 mi
Registration #18	2024-02-20	51.208 mi
Registration #19	2025-02-20	51.208 mi
Registration #20	2026-02-20	51.208 mi
Registration #21	2027-02-20	51.208 mi
Registration #22	2028-02-20	51.208 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1648 mm
Height	1460 mm
Length	3525 mm
Wheel base	2321 mm
Kerb weight	920 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	34 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BBY490728