



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PREVIA VVTI GS 8 STR
Colour	Green
Year of manufacture	2001
Top speed	111 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	225 Nm at 4.000 rpm
Engine capacity	2.362 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.3 mpg
Consumption extra urban	35.8 mpg
Consumption combined	30.1 mpg
CO2 emission	228 g/km
CO2 label	L







Internet history

Entry 1

Date	2021-06-25
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-08-24
MOT pass rate	60 %
MOT passed	15
Failed MOT tests	10
Total advice items	48
Total items failed	30

MOT #252021-08-25 15:19

MOT test number811378602464

Result✓ Passed

Next expiry date2022-08-24

Advice	Oil leak under.
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pipe slightly damaged (1.1.11 (c))
Advice	Offside Front small pin hole in CV boot
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Brake pipe slightly damaged (1.1.11 (c))

**MOT #24**

2021-08-25 15:19

MOT test number

840263139206

Result**✗ Failed****Pass with rectification** Headlamp light intensity severely reduced Both (4.1.4 (a))**Pass with rectification** Front Exhaust silencer insecure (8.1.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe slightly damaged (1.1.11 (c))**Advice** Offside Front small pin hole in CV boot**Pass with rectification** Central Rear Seat belt buckle missing (7.1.2 (d))**Pass with rectification** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pipe slightly damaged (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak under.**MOT #23**

2020-08-06 08:16

MOT test number

762020815896

Result**✓ Passed****MOT #22**

2020-08-05 10:46

MOT test number

534502127122

Result**✗ Failed****Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**DANGEROUS** Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))**MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #21** 2019-08-16 08:47**MOT test number** 377109376395**Result** ✓ Passed**MOT #20** 2016-06-25 11:02**MOT test number** 641282880533**Result** ✓ Passed**MOT #19** 2016-06-14 14:16**MOT test number** 512152349644**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Registration plate lamp not working both (1.1.C.1d)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Ball joint has excessive play (2.2.B.1f)**Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)**MOT #18** 2015-06-04 16:34**MOT test number** 586215955123**Result** ✓ Passed**MOT #17** 2015-05-29 15:52**MOT test number** 589879145121**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Battery insecure (1.9.1)

**MOT #16**

2014-04-29 15:14

MOT test number

238339814414

Result

✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Oil leak

Advice Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #15

2014-04-16 16:44

MOT test number

949226804149

Result

✗ Failed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Oil leak

Fail Nearside Stop lamp not working (1.2.1b)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Battery insecure (1.9.1)

MOT #14

2013-04-15 14:41

MOT test number

839065103162

Result

✓ Passed

MOT #13

2012-04-12 09:15

MOT test number

587583002178

Result

✓ Passed

**MOT #12**

2012-04-04 13:17

MOT test number

839685492015

Result

✗ Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)**MOT #11**

2011-06-23 12:14

MOT test number

298184871455

Result

✓ Passed

MOT #10

2011-06-23 10:00

MOT test number

819134571131

Result

✗ Failed

Notice Offside front wiper split**Notice** Offside front lower balljoint rubber boot split**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Nearside rear lamp lense cracked**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Front pads low**Advice** Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Offside rear brake pipe corroded**Notice** Both front lower wishbone rear bushes starting to split**Fail** Offside Rear Exhaust system not adequately supported (7.1.1)**Fail** Centre Body insecure and dangerous to other road users (6.1.B.1b)**Notice** 2.5 mm tread on offside rear tyre**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



MOT #9	2010-06-29 08:31
MOT test number	984680780110
Result	✓ Passed

MOT #8	2010-06-25 09:12
MOT test number	580236070177
Result	✗ Failed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Notice** Nail in offside rear tyre
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Notice** Engine management light on
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2009-07-15 17:46
MOT test number	464316399120
Result	✓ Passed

**MOT #6** 2009-07-15 12:36**MOT test number** 223536499104**Result** ✗ Failed**Notice** Front pads low 4mm left**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Rear brake disc excessively pitted (3.5.1h)**Notice** Both front lower wishbones perished bushes**Fail** Offside Rear Brake pad(s) has restricted free movement (3.5.1k)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2008-07-15 11:52**MOT test number** 612567798179**Result** ✓ Passed**MOT #4** 2008-04-15 15:04**MOT test number** 242396108133**Result** ✓ Passed**MOT #3** 2007-04-11 16:55**MOT test number** 781341107125**Result** ✓ Passed



MOT #2

2007-04-11 14:07

MOT test number

650801407135

Result

✖ Failed

Advice

Nearside Front brake disc slightly scored (3.5.1h)

Advice

Offside Rear brake disc slightly pitted (3.5.1h)

Fail

Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Front brake disc slightly scored (3.5.1h)

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1

2006-04-12 09:55

MOT test number

704902206147

Result

✔ Passed




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	Y57BBD
Plate since	2019-03-28
Current registration	Y57BBD
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2001-05-22
Last registration	2021-08-25
Complete history	See info



Registration #1	2001-05-22	12 mi
Registration #2	2006-04-12	55.247 mi
Registration #3	2007-04-11	62.720 mi
Registration #4	2007-04-11	62.720 mi
Registration #5	2008-04-15	69.371 mi
Registration #6	2008-07-15	70.211 mi
Registration #7	2009-07-15	79.646 mi
Registration #8	2009-07-15	79.646 mi
Registration #9	2010-06-25	86.187 mi
Registration #10	2010-06-29	86.360 mi
Registration #11	2011-06-23	94.341 mi
Registration #12	2011-06-23	94.341 mi
Registration #13	2012-04-04	98.538 mi
Registration #14	2012-04-12	98.799 mi
Registration #15	2013-05-22	101.377 mi
Registration #16	2013-05-22	101.377 mi
Registration #17	2013-05-22	101.377 mi
Registration #18	2013-05-22	101.377 mi
Registration #19	2013-05-22	101.377 mi
Registration #20	2013-05-22	101.377 mi
Registration #21	2013-05-22	101.377 mi
Registration #22	2013-05-22	101.377 mi
Registration #23	2013-05-22	101.377 mi
Registration #24	2013-05-22	101.377 mi
Registration #25	2013-05-22	101.377 mi
Registration #26	2013-05-22	101.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1790 mm
Height	1770 mm
Length	4750 mm
Wheel base	2900 mm
Kerb weight	1600 kg

Additional information

Fuel tank capacity	76 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2AZ0488767