





report date: 2024-03-28

#### General information

Make	VAUXHALL
Model	ASTRA SRI ECOTEC S/S
Colour	Blue
Year of manufacture	2018
Top speed	121 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	104 BHP
Max. torque	170 Nm at 4.250 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 3

Date 2021-08-22

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date	2021-07-03	


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

<b>-</b> .	
Date	2021-06-27
Date	2021-00-27

Pictures 8

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-31
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #5		2023-08-04 12:37
MOT test numb	per	117519701299
Result		✓ Passed
Next expiry da	te	2024-08-31
<b>Advice</b> Nea	rside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
<b>Advice</b> Offs	ide Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #4		2022-08-10 12:54
MOT test	number	801152378047
Result		✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #3	2021-09-01 09:40
MOT test number	984310642801
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2

MOT test number

643544429979

Result

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #1

MOT test number

112283607103

Result

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))


Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	31 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloahere.	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-23
Last registration	2023-08-04
Complete history	See info



Registration #1	2018-04-23	25 mi
Registration #2	2021-02-17	23.128 mi
Registration #3	2021-02-18	23.128 mi
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		D.777 66
Registration #8		71.777 66
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	83%
Safety systems	75%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	2042 mm
Height	1485 mm
Length	4370 mm
Wheel base	2662 mm
Kerb weight	1188 kg
Max. allowed weight	1780 kg

## Additional information

Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	B1181157HRYX0127LE1

CarCheck.co.uk page 11/11