



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI (125PS)
Colour	Blue
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	166 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-18
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-14
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	44
Total items failed	12

MOT #20	2023-09-01 12:00
MOT test number	983958506438
Result	✓ Passed
Next expiry date	2024-09-14
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Centre stop lamp not working
Advice	Items removed from driver's view prior to test
Advice	Offside washer jet weak

MOT #19	2022-09-13 14:20
MOT test number	919493888568
Result	✓ Passed
Advice	Central stop lamp inoperative

**MOT #18**

2022-09-13 10:07

**MOT test number**

846131445136

**Result****✗ Failed****Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Power steering fluid level below minimum (2.1.5 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Seat belt buckle not functioning as intended centre seat row (7.1.2 (d))**Advice** Central stop lamp inoperative**MOT #17**

2021-09-15 11:43

**MOT test number**

249140699307

**Result****✓ Passed****MOT #16**

2021-07-26 16:09

**MOT test number**

990144811939

**Result****✗ Failed****Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))**Advice** Parking brake lever has little reserve travel**Advice** Tyre worn close to legal limit/worn on edge All four tyres (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**MOT #15**

2020-12-04 11:05

**MOT test number**

837936534756

**Result****✓ Passed****Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14** 2019-12-02 10:54**MOT test number** 892268504147**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2018-11-28 11:55**MOT test number** 856359392488**Result** ✓ Passed**MOT #12** 2017-11-21 10:32**MOT test number** 581888856397**Result** ✓ Passed**MOT #11** 2016-12-02 09:37**MOT test number** 514063869851**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2016-12-01 09:25**MOT test number** 256303648393**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2015-11-26 12:33**MOT test number** 851370278098**Result** ✓ Passed

- Advice** O/s rear tyre perished on sidewall
- Advice** Brake pad(s) wearing thin all front (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit on 2.5 mm (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit on 2.5 mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit on 2mm (4.1.E.1)

**MOT #8** 2015-11-26 12:33**MOT test number** 489609422280**Result** ✗ Failed

- Advice** Brake pad(s) wearing thin all front (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit on 2.5 mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit on 2mm (4.1.E.1)
- Advice** O/s rear tyre perished on sidewall
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Nearside Front Tyre worn close to the legal limit on 2.5 mm (4.1.E.1)

**MOT #7**

2014-11-25 10:30

**MOT test number**

759799824350

**Result**

✓ Passed

- Notice** Child seat fitted to nearside rear seat
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6**

2014-11-12 10:30

**MOT test number**

868406514325

**Result**

✗ Failed

- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Child seat fitted to nearside rear seat

**MOT #5**

2013-10-31 12:41

**MOT test number**

285254803348

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-11-01 13:40**MOT test number** 448216602461**Result** ✓ Passed**MOT #3** 2012-11-01 10:38**MOT test number** 495876302462**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2011-11-03 12:23**MOT test number** 318137901339**Result** ✓ Passed**MOT #1** 2011-11-03 12:23**MOT test number** 409017801350**Result** ✗ Failed**Pass with rectification** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	14 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>EA58BYC</b>
Plate since	2024-03-29
Current registration	<b>EA58BYC</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-11-10
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2008-11-10	22 mi
Registration #2	2011-11-03	24.600 mi
Registration #3	2012-11-01	32.825 mi
Registration #4	2012-11-01	32.825 mi
Registration #5	2013-10-31	39.605 mi
Registration #6	2014-11-12	44.343 mi
Registration #7	2014-11-25	44.462 mi
Registration #8	2015-11-26	49.150 mi
Registration #9	2015-11-26	49.150 mi
Registration #10	2016-12-01	54.114 mi
Registration #11	2016-12-02	54.133 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi
Registration #17	2019-05-29	55.277 mi
Registration #18	2019-05-29	55.277 mi
Registration #19	2019-05-29	55.277 mi
Registration #20	2019-05-29	55.277 mi
Registration #21	2019-05-29	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1807 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

8K54165