





report date: 2024-03-29

#### General information

Make	FORD
Model	FIESTA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



RE10RHZ
report date: 2024-03-29

### Internet history

#### Entry 3

Date 2023-01-07

Pictures 20

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 2

Date 2021-07-02

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

Entry 1

Date 2021-06-06

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	10
Total items failed	1

MOT #15	2024-01-03 13:32
MOT test number	214913158431
Result	✓ Passed
Next expiry date	2025-01-05

MOT #14	2024	4-01-03 13:32
MOT test number	3	72988407998
Result		<b>X</b> Failed
Pass with rectification	Offside Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #13	2023-01-06 13:20
MOT test number	812754929399
Result	<b>✓</b> Passed
MOT #12	2022-04-29 10:19
MOT test number	190133093625
Result	<b>✓</b> Passed
Advice Bonnet been secured down in the closed position be	out will require future attention

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #11** 2022-04-29 09:59

**MOT test number** 902050356239

**Result** X Failed

MAJOR Central Front Bonnet cannot be secured in the closed position (3.1 (b) (i))

MOT #10 2021-05-24 17:07

MOT test number 896737316370

Result \( \sqrt{Passed} \)

Advice Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))

Advice Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))

MOT #9 2021-05-22 10:45

MOT test number 246129000888

**Result** X Failed

Advice Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))

**Advice** Coolant leak

**Advice** Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))

**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #8 2020-06-26 15:38

**MOT test number** 769524806353

**Result** ✓ Passed

**MOT #7** 2019-06-05 14:44

**MOT test number** 928344809935

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6	2018-06-13 10:35
MOT test number	199616444471
Result	✓ Passed
MOT #5	2017-06-15 09:59
MOT test number	685463575762
Result	✓ Passed
MOT #4	2016-06-22 15:50
MOT test number	959070452816
Result	✓ Passed
MOT #3	2015-06-15 12:31
MOT test number	167166365188
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #2	2014-06-11 13:09

MOT #2	2014-06-11 13:09
MOT test number	977032164195
Result	<b>✓</b> Passed
MOT #1	2013-06-18 12:51
MOT test number	845959663142
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



RE10RHZ
report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	5 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
********	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	IK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-24
Last registration	2024-01-03
Complete history	See info



Registration #1	2010-06-24	11 mi
Registration #2	2013-06-18	22.705 mi
Registration #3	2014-06-11	27.173 mi
Registration #4	2015-06-15	32.159 mi
Registration #5	2016-06-22	37.149 mi
Registration #6	2017-06-15	41.760 mi
Registration #7	2018-06-13	46.466 mi
Registration #8	2019-06-05	51.353 mi
Registration #9	2020-06-26	55.960 mi
Registration #10	2021-05-22	60.253 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12