





report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2014
Top speed	98 mph
0 - 60 mph	5.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	136 g/km
CO2 label	Е



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-11-28

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT	history
-----	---------

MOT expiry date	2024-10-19
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	12
Total items failed	9

MOT #13	2023-10-20 15:24
MOT test number	653000767778
Result	✓ Passed
Next expiry date	2024-10-19
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-10-20 08:56
MOT test number	840504911231
Result	🗙 Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #11	2022-11-29 14:29
MOT test number	958411998615
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT test number

FL14FKA report date: 2024-03-28

174659734965

MOT test number

Result

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #9 2021-12-06 08:56

MOT test number 944223989963

Result ✓ Passed

MOT #8 2021-07-23 12:02

MOT test number 583547999737

Result ✓ Passed

MOT #7 2020-06-26 15:14

MOT test number 778672967429

Result Passed

MOT #6 2019-11-11 15:20

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



MOT #5 2019-02-26 12:44

MOT test number 146513376749

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Non obligatory mirror damaged

MOT #4 2019-02-26 12:44

MOT test number 721021527911

Result X Failed

Advice Offside Front Non obligatory mirror damaged

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3 2018-04-24 11:56

MOT test number 935595909084

Result

Passed

MOT #2 2017-03-23 13:52

MOT test number 875749461537

Result
✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2017-03-23 13:52

MOT test number 601800191574

Result ★ Failed

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification Nearside Side repeater incorrect colour (1.4.A.2f)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
2000000	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-27
Last registration	2023-10-20
Complete history	See info



Registration #1	2014-03-27	22 mi
Registration #2	2017-03-23	49.039 mi
Registration #3	2017-03-23	49.039 mi
Registration #4	2018-04-24	59.974 mi
Registration #5	2019-02-26	64.986 mi
Registration #6	2019-02-26	64.986 mi
Registration #7	2019-11-11	68.364 mi
Registration #8	2020-06-26	71.192 mi
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	5279190

CarCheck.co.uk page 13/13