





report date: 2024-03-29

General information

| Make | VOLVO |
|---------------------|---------------------|
| Pidre | VOLVO |
| Model | V60 D4 R-DESIGN NAV |
| Colour | White |
| Year of manufacture | 2017 |
| Top speed | 140 mph |
| 0 - 60 mph | 7.2 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 116 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history


Entry 1

Date 2022-01-26

Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-08-13 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 8 |
| Total items failed | 0 |

| MOT #4 | | 2023-07-25 07:55 |
|---|--|--------------------|
| MOT test | number | 466946799976 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-08-13 |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Front Lower engine trays fitted | |
| Advice | Advice Front Brake pad(s) wearing thin offside and nearside inners (1.1.13 (a) (ii)) | |
| Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened offside and nearside inners lipped (1.1.14 (a) (ii)) | | fside and nearside |
| Advice | Rear Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i) |)) |

| MOT #3 | | 2022-07-30 08:00 |
|----------|---|------------------|
| MOT test | number | 883084197459 |
| Result | | ✓ Passed |
| Advice | Rear Lower Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Front lower engine tray fitted | |
| Advice | Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #2 | 2021-08-03 08:00 |
|-----------------|------------------|
| MOT test number | 123336050852 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2020-08-14 11:26
MOT test number 540317119344

Result ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 13 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|--|-------------|
| | |
| manus . | |
| | |
| ************* | |
| | |
| THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | |
| Current registration | NK UK |
| Flate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-10-27 |
| Last registration | 2023-07-25 |
| Complete history | See info |



| Registration #1 | 2017-10-27 | 21 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-08-14 | 20.290 mi |
| Registration #3 | 2021-08-03 | 24.893 mi |
| Registration #4 | | 71.777 66 |
| Registration #5 | | 11.777 es |
| Registration #6 | | n.m. |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 95% |
| Children | 80% |
| Pedestrian | 76% |
| Safety systems | 93% |
| Overall rating | 88% |
| Video | see crash video |



Dimensions & weight

| Width | 2097 mm |
|---------------------|---------|
| Height | 1484 mm |
| Length | 4635 mm |
| Wheel base | 2776 mm |
| Kerb weight | 1663 kg |
| Max. allowed weight | 2200 kg |

Additional information

| Fuel tank capacity | 67 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/3 |

Number of axles 2

Engine number 2227886