



HYUNDAI



SKIIONN


report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	194 g/km
CO2 label	J





## MOT history

MOT expiry date	2022-06-07
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #11	2021-06-02 11:39
MOT test number	593431845343
Result	✓ Passed
Next expiry date	2022-06-07

MOT #10	2020-06-08 08:24
MOT test number	287527722842
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Coil spring corroded both rear springs (5.3.1 (b) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2020-06-08 08:24
MOT test number	321284475545
Result	✗ Failed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Coil spring corroded both rear springs (5.3.1 (b) (i))

**MOT #8** 2019-04-03 08:10**MOT test number** 352254714551**Result** ✓ Passed**Advice** Brake pad(s) wearing thin all. (1.1.13 (a) (ii))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**MOT #7** 2018-04-04 07:50**MOT test number** 725220976156**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear coil spring corroded (2.4.C.1b)**MOT #6** 2018-04-04 07:50**MOT test number** 145229593345**Result** ✗ Failed**Advice** Rear coil spring corroded (2.4.C.1b)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2017-03-06 10:15**MOT test number** 303023550748**Result** ✓ Passed**MOT #4** 2016-03-07 13:28**MOT test number** 316004573764**Result** ✓ Passed

**MOT #3** 2015-03-05 14:59**MOT test number** 715234465047**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2015-03-05 14:59**MOT test number** 796474965085**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-02-10 16:12**MOT test number** 438751344078**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-03-08
Last registration	2021-06-02
Complete history	<a href="#">See info</a>



Registration #1	2011-03-08	26 mi
Registration #2	2014-02-10	42.393 mi
Registration #3	2015-03-05	53.911 mi
Registration #4	2016-03-07	64.018 mi
Registration #5	2017-03-06	74.750 mi
Registration #6	2018-04-04	86.798 mi
Registration #7	2019-05-29	95.277 mi
Registration #8	2020-05-29	101.277 mi
Registration #9	2020-05-29	101.277 mi
Registration #10	2020-05-29	101.277 mi
Registration #11	2021-06-02	101.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D4HBAU305160
---------------	--------------