



report date: 2024-03-29

General information

Make	FIAT
Model	DUCATO 30 P/V MULTIJET
Colour	White
Year of manufacture	-
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	300 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-04
Pictures	10
Listing price	View report



source: cargurus.co.uk

**MOT history****MOT #11**

2022-12-19 17:15

MOT test number

119587034112

Result**✗ Failed**

- Advice** Nearside Front Play in steering rack inner joint(s) and or ram
- Fail** Nearside Front Steering system excessively rough top mount (2.1.1 (a))
- Advice** Exhaust has a minor leak of exhaust gases engine bay (6.1.2 (a))
- Fail** Nearside Front Body component damaged and likely to cause injury mirror housing (6.2.1 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Front Windscreen washer not working (3.5 (a))
- Fail** Exhaust particulate filter obviously modified (8.2.2.1 (a))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Exhaust centre box corroded
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #10

2021-10-13 06:39

MOT test number

731403532314

Result**✓ Passed**

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated leaking (6.1.7 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 215/70/15 (5.2.3 (e))

**MOT #9** 2021-10-10 07:42**MOT test number** 495717987492**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 215/70/15 (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated leaking (6.1.7 (g) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #8** 2020-10-17 10:14**MOT test number** 171518855953**Result** ✓ Passed**MOT #7** 2019-10-14 12:59**MOT test number** 125623679681**Result** ✓ Passed**MOT #6** 2019-10-12 08:26**MOT test number** 283159833949**Result** ✗ Failed**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake lining(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #5** 2018-11-24 11:53**MOT test number** 481541139466**Result** ✓ Passed**Advice** Offside Front track rod end**Advice** Offside Front inner rack**Advice** Nearside front inner rack**MOT #4** 2017-08-23 09:17**MOT test number** 617593339301**Result** ✓ Passed**Advice** Play in steering rack joints**MOT #3** 2016-08-11 13:37**MOT test number** 697689303229**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2016-08-11 13:00**MOT test number** 675958384777**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #1** 2015-08-15 08:48**MOT test number** 337405015497**Result** ✓ Passed**Advice** EML light on



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-01
Last registration	2022-12-19
Complete history	See info



Registration #1	2012-09-01	6 mi
Registration #2	2015-08-15	191.868 mi
Registration #3	2016-08-11	290.578 mi
Registration #4	2016-08-11	290.578 mi
Registration #5	2017-08-23	377.930 mi
Registration #6	2018-11-24	407.748 mi
Registration #7	2019-05-29	51.277 mi
Registration #8	2019-05-29	51.277 mi
Registration #9	2019-05-29	51.277 mi
Registration #10	2019-05-29	51.277 mi
Registration #11	2019-05-29	51.277 mi
Registration #12	2019-05-29	51.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	1545902