



report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS EGS PICASSO
Colour	Brown
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg





Internet history

Entry 1

Date	2021-11-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #18	2022-10-06 08:46
MOT test number	343643998380
Result	✓ Passed
Next expiry date	2023-10-20
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Shoulders (5.2.3 (e))
Advice	Undertray fitted obscuring some components
Advice	Nearside Front Nail in tyre

MOT #17	2021-10-07 10:34
MOT test number	937988223616
Result	✓ Passed

MOT #16	2021-10-06 10:10
MOT test number	237706376984
Result	✗ Failed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Front Position lamp not working Both (4.2.1 (a) (ii))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #15	2020-10-21 13:15
MOT test number	738435285380
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))

**MOT #14**

2020-10-20 12:02

MOT test number

111977418869

Result

✗ Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**MAJOR** Front Position lamp not working Both (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))**MOT #13**

2019-04-08 10:50

MOT test number

328940768368

Result

✓ Passed

Advice Towbar slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #12**

2018-05-01 19:06

MOT test number

710808333922

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Towbar component slightly corroded (6.6.1)

**MOT #11** 2018-05-01 10:21**MOT test number** 567639317076**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Towbar component slightly corroded (6.6.1)**MOT #10** 2017-04-06 09:28**MOT test number** 681481632586**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-04-06 09:28**MOT test number** 956398763211**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #8** 2016-04-12 10:10**MOT test number** 768020987643**Result** ✓ Passed



MOT #7	2016-04-12 10:10
MOT test number	344044407002
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Nearside Headlamp aim too low (1.8)

MOT #6	2015-04-08 17:16
MOT test number	617658195048
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	All 4 tyres cracking
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #5 2015-04-08 17:16

MOT test number 769658495014

Result ✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Notice All 4 tyres cracking

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2014-04-25 14:22

MOT test number 398035914107

Result ✓ Passed

Notice Unable to see brakes fully

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay



MOT #3	2014-04-25 14:22
MOT test number	977205514141
Result	✗ Failed
Notice	Unable to see brakes fully
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Notice	Engine covers fitted obscuring some components in the engine bay
Pass with rectification	Offside Front Headlamp aim too high (1.8)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Nearside Front Headlamp aim too high (1.8)

MOT #2	2013-03-21 12:47
MOT test number	767110783068
Result	✓ Passed

MOT #1	2013-03-21 12:47
MOT test number	355370883080
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Offside Headlamp aim too low (1.8)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-26
Last registration	2022-10-06
Complete history	See info



Registration #1	2010-04-26	10 mi
Registration #2	2013-03-21	15.904 mi
Registration #3	2014-04-25	26.131 mi
Registration #4	2015-04-08	33.950 mi
Registration #5	2016-04-12	41.265 mi
Registration #6	2016-04-12	41.265 mi
Registration #7	2017-04-06	49.587 mi
Registration #8	2017-04-06	49.587 mi
Registration #9	2018-05-01	61.318 mi
Registration #10	2019-05-01	75.377 mi
Registration #11	2019-05-01	75.377 mi
Registration #12	2019-05-01	75.377 mi
Registration #13	2019-05-01	75.377 mi
Registration #14	2019-05-01	75.377 mi
Registration #15	2019-05-01	75.377 mi
Registration #16	2019-05-01	75.377 mi
Registration #17	2019-05-01	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1830 mm
Height	1680 mm
Length	4470 mm
Wheel base	2728 mm
Kerb weight	1499 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBN0277393