



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	White
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-10-24
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	25
Total items failed	6

MOT #11 2023-10-16 11:04

MOT test number 167301457435

Result ✓ Passed

Next expiry date 2024-10-24

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2023-10-11 08:56

MOT test number 113751640035

Result ✗ Failed

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #9** 2022-10-06 10:21**MOT test number** 296139819444**Result** ✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #8** 2021-10-05 14:59**MOT test number** 954470412888**Result** ✓ Passed**MOT #7** 2020-10-08 14:33**MOT test number** 100558977592**Result** ✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both discs inner faces (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs inner faces (1.1.14 (a) (ii))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #6** 2020-10-08 13:15**MOT test number** 602700831731**Result** ✗ Failed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs inner faces (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Fail** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both discs inner faces (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #5** 2019-10-08 10:37**MOT test number** 472070792839**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #4** 2018-10-02 14:03**MOT test number** 892421076849**Result** ✓ Passed**MOT #3** 2018-10-02 14:03**MOT test number** 470225012362**Result** ✗ Failed**Pass with rectification** Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #2	2017-10-25 14:36
MOT test number	239116569059
Result	✓ Passed

MOT #1	2017-02-20 15:36
MOT test number	363334053914
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-01
Last registration	2023-10-16
Complete history	<a href="#">See info</a>



Registration #1	2014-03-01	6 mi
Registration #2	2017-02-20	22.392 mi
Registration #3	2017-10-25	29.400 mi
Registration #4	2018-10-02	41.561 mi
Registration #5	2018-10-02	41.561 mi
Registration #6	2019-10-08	52.833 mi
Registration #7	2020-10-08	61.583 mi
Registration #8	2020-10-08	61.583 mi
Registration #9	2020-10-08	61.583 mi
Registration #10	2020-10-08	61.583 mi
Registration #11	2020-10-08	61.583 mi
Registration #12	2020-10-08	61.583 mi
Registration #13	2020-10-08	61.583 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3167254