



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V BMT HIGHLINE
Colour	White
Year of manufacture	2015
Top speed	101 mph
0 - 100 km/h	19.7 seconds
0 - 60 mph	14.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 kW / 84 HP / 113 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	46.3 mpg
Consumption combined	40.4 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-30
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	25
Total items failed	2

MOT #10	2023-06-23 09:26
MOT test number	880159253942
Result	✓ Passed
Next expiry date	2024-06-27
Minor	Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9	2022-06-28 07:10
MOT test number	428943182683
Result	✓ Passed
Minor	Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8	2021-06-11 12:51
MOT test number	678206059753
Result	✓ Passed
Advice	Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #7**

2021-06-02 13:26

MOT test number

898705628568

Result

✗ Failed

Advice Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))**MOT #6**

2020-08-03 13:55

MOT test number

300088999873

Result

✓ Passed

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5**

2020-08-03 13:55

MOT test number

400427437272

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #4** 2019-08-17 08:18**MOT test number** 185825072822**Result** ✓ Passed

Minor Front Windscreen damaged but not adversely affecting driver's view SMALL STONE CHIP (3.2 (a) (i))

MOT #3 2019-08-16 11:04**MOT test number** 879126651560**Result** ✗ Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Front Lower Engine mounting damaged or deteriorated resulting in excessive movement BAD SPLIT (6.1.8 (a) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view SMALL STONE CHIP (3.2 (a) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2018-08-01 10:56**MOT test number** 445814667669**Result** ✓ Passed

Advice Central Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

MOT #1 2018-08-01 10:56**MOT test number** 943700236699**Result** ✗ Failed

Advice Central Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

Pass with rectification Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
27 June 2024

Tax status		Valid until 1 July
Days left		63
MOT expiry date		27 June 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LB15MJO
Plate since	2019-06-29
Current registration	 LB15MJO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-08-18
Last registration	2023-06-23
Complete history	See info



Registration #1	2015-08-18	29 mi
Registration #2	2018-08-01	110.548 mi
Registration #3	2018-08-01	110.548 mi
Registration #4	2019-08-16	116.348 mi
Registration #5	2019-08-17	116.349 mi
Registration #6	2020-08-03	120.587 mi
Registration #7	2020-08-03	120.587 mi
Registration #8	2020-08-03	120.587 mi
Registration #9	2020-08-03	120.587 mi
Registration #10	2020-08-03	120.587 mi
Registration #11	2020-08-03	120.587 mi
Registration #12	2020-08-03	120.587 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3400 mm
Kerb weight	1918 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CAAD864320