



RENAULT




report date: 2024-03-28

General information

| | |
|---------------------|-----------------------------------|
| Make | RENAULT |
| Model | SCENIC DYNAMIQUE DCI 130 G/SCENIC |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 119 mph |
| 0 - 60 mph | 9.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 130 BHP |
| Max. torque | 300 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-08-03 |
| Pictures | 45 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-02 |
| Pictures | 45 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|------------------|
| MOT #18 | 2020-12-18 14:54 |
| MOT test number | 603740108296 |
| Result | ✓ Passed |
| Next expiry date | 2021-12-18 |

| | |
|------------------------|------------------|
| MOT #17 | 2020-12-17 14:42 |
| MOT test number | 896937700140 |
| Result | ✗ Failed |

Advice Front Play in steering rack inner joint(s) Near side and off side front

Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

| | |
|------------------------|------------------|
| MOT #16 | 2019-12-19 14:15 |
| MOT test number | 968481855976 |
| Result | ✓ Passed |

**MOT #15**

2019-11-18 10:13

MOT test number

335518663228

Result**✗ Failed**

- Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14

2018-11-15 17:06

MOT test number

403081909675

Result**✓ Passed**

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Play in steering rack inner joint(s)

**MOT #13** 2018-11-15 09:46**MOT test number** 733884231197**Result** ✗ Failed

- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps o/s and n/s (4.7.1 (b) (ii))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #12 2017-11-15 11:11**MOT test number** 418004041220**Result** ✓ Passed

- Advice** Offside Play in steering rack inner joint(s)
- Advice** Nearside Play in steering rack inner joint(s)

MOT #11 2017-11-14 11:29**MOT test number** 299149466994**Result** ✗ Failed

- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Nearside Play in steering rack inner joint(s)

**MOT #10** 2016-11-01 09:52**MOT test number** 870985563465**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #9** 2015-10-20 11:42**MOT test number** 989453040082**Result** ✓ Passed**Advice** Steering rack inner joints worn.**MOT #8** 2015-10-19 14:22**MOT test number** 175348147826**Result** ✗ Failed**Fail** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Steering rack inner joints worn.**Fail** Battery insecure (1.9.1)**MOT #7** 2014-10-29 09:39**MOT test number** 326812204390**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**MOT #6** 2013-11-15 10:18**MOT test number** 419359113448**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2013-01-16 15:06**MOT test number** 588796213096**Result** ✓ Passed**MOT #4** 2012-03-01 15:19**MOT test number** 155191062073**Result** ✓ Passed**Notice** Slight play in both front rackarms**MOT #3** 2011-02-24 09:40**MOT test number** 879185251057**Result** ✓ Passed**Notice** Play in both rack arms**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front discs pitted**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-03-11 12:22**MOT test number** 152540070044**Result** ✓ Passed**Advice** Nearside Front Ball joint has slight play (2.2.B.1f)**Advice** Rear brake disc slightly pitted (3.5.1h)**Advice** Offside Front Ball joint has slight play (2.2.B.1f)



MOT #1 2009-03-12 09:56

MOT test number 934711879050

Result ✓ Passed

Notice Rear wiper split

Advice Offside Front Steering pivot point has slight play (2.2.B.1g)

Advice Nearside Front Steering pivot point has slight play (2.2.B.1g)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|---------|------|
| Finance company | RENAULT | 2024 |
| Date of agreement | RENAULT | 2024 |
| Agreement type | RENAULT | 2024 |
| Agreement term | RENAULT | 2024 |
| Agreement number | RENAULT | 2024 |
| Contact info | RENAULT | 2024 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2006-03-22 |
| Last registration | 2020-12-18 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-03-22 | 11 mi |
| Registration #2 | 2009-03-12 | 25.556 mi |
| Registration #3 | 2010-03-11 | 35.473 mi |
| Registration #4 | 2011-02-24 | 43.754 mi |
| Registration #5 | 2012-03-01 | 54.181 mi |
| Registration #6 | 2013-01-16 | 60.188 mi |
| Registration #7 | 2013-11-15 | 66.900 mi |
| Registration #8 | 2014-10-29 | 75.153 mi |
| Registration #9 | 2015-10-19 | 82.357 mi |
| Registration #10 | 2015-10-20 | 82.357 mi |
| Registration #11 | 2016-11-01 | 89.355 mi |
| Registration #12 | 2016-11-01 | 89.355 mi |
| Registration #13 | 2016-11-01 | 89.355 mi |
| Registration #14 | 2016-11-01 | 89.355 mi |
| Registration #15 | 2016-11-01 | 89.355 mi |
| Registration #16 | 2016-11-01 | 89.355 mi |
| Registration #17 | 2016-11-01 | 89.355 mi |
| Registration #18 | 2016-11-01 | 89.355 mi |
| Registration #19 | 2016-11-01 | 89.355 mi |
| Registration #20 | 2016-11-01 | 89.355 mi |
| Registration #21 | 2016-11-01 | 89.355 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2087 mm |
| Height | 1717 mm |
| Length | 4493 mm |
| Wheel base | 2736 mm |
| Kerb weight | 1530 kg |
| Max. allowed weight | 2195 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | C045999 |