





report date: 2024-03-28

#### General information

Make	FORD
Model	B-MAX ZETEC
Colour	Red
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	89 BHP
Max. torque	128 Nm at 4.000 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

#### Internet history

#### Entry 3

 Date
 2023-07-12

 Pictures
 0

Listing price <u>View report</u>

source: carcraft.co.uk

#### Entry 2

Date 2021-07-05

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1


Date 2021-07-04

Pictures

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1010		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-07-17
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	6
Total items failed	1

MOT #7	2023-07-18 12:30
MOT test number	320440898552
Result	✓ Passed
Next expiry date	2024-07-17

MOT #6		2022-06-25 15:23
MOT test	number	773343443802
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2021-07-08 17::	13
MOT test	number 17415733856	56
Result	✓ Passe	ed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking in the treads (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2020-09-28 09:38
MOT test number	605351036579
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2019-09-24 12:12

**MOT test number** 474947146949

**Result** ✓ Passed

MOT #2 2018-09-14 11:28

MOT test number 775310760301

**Result** 
✓ Passed

Minor Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #1 2018-09-14 11:28

**MOT test number** 535541007998

**Result** X Failed

**Pass with rectification** Offside Obligatory mirror missing (3.3 (a))

Minor Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	17 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

o which history		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?
MANAGEMENT CONTRACTOR		
***************************************		
***************************************		
**************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		
Current registration	NK SIN	HII
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



EO65XRA report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-30
Last registration	2023-07-18
Complete history	See info



Registration #1	2015-09-30	26 mi
Registration #2	2018-09-14	17.519 mi
Registration #3	2018-09-14	17.519 mi
Registration #4	2019-09-24	23.273 mi
Registration #5	2020-09-28	28.142 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11



EO65XRA report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

### Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



### Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1720 kg

## Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11