





report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Black
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I



CarCheck.co.uk page 1/13



LT08RYB

report date: 2024-03-29

Internet history


Entry 1

Date 2021-11-27

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-01-11
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	18
Total items failed	2

MOT #16		2023-01-04 14:15
MOT test nu	mber	895477060912
Result		✓ Passed
Next expiry	date	2024-01-11
Advice N	earside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice 0	offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice O	offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #15	2022-01-12 17:28
MOT test number	546248896181
Result	✓ Passed
MOT #14	2021-04-27 10:23
MOT test number	658999835846
Result	✓ Passed
MOT #13	2020-06-26 10:31
MOT test number	893497479974
Result	✓ Passed

CarCheck.co.uk page 3/13



 MOT #12
 2019-05-23 10:37

 MOT test number
 500833893045

 Result
 ✓ Passed

 MOT #11
 2019-05-23 10:37

 MOT test number
 336336386324

 Result
 X Failed

 Pass with rectification

 Offside Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #10
 2018-05-29 12:04

 MOT test number
 832042215007

 Result
 ✓ Passed

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

All springs corroded

Advice

Rear Stop lamp slightly affected by the operation of another lamp both (1.2.1f)

Advice

Osr nsr tyres perrished

CarCheck.co.uk page 4/13



LT08RYB

report date: 2024-03-29

MOT #8 2017-06-15 08:09 599814114659 **MOT** test number Result × Failed **Advice** Rear Stop lamp slightly affected by the operation of another lamp both (1.2.1f) Advice All springs corroded Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Front Headlamp aim too high (1.8) **Advice** Osr nsr tyres perrished

MOT #7

MOT test number

772316792538

Result

Advice Both front tyres perishing

MOT #6

MOT test number

2015-06-09 10:24

MOT test number

217860065153

Result

✓ Passed

Notice Nail in offside front tyre

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Nearside rear tyre worn on inner edge

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



Result

LTO8RYB report date: 2024-03-29

✓ Passed

MOT #4		2013-06-12 10:50
MOT test	number	957813863172
Result		✓ Passed
Notice	Offside front tyre wearing on outer edge	
Notice	Offside rear tyre perishing	

Notice Offside rear tyre perishing	
MOT #3	2012-06-30 12:43
MOT test number	276502082415
Result	✓ Passed
MOT #2	2011-06-10 16:56
MOT test number	307481461134
Result	✓ Passed
MOT #1	2011-01-18 12:07
MOT test number	406838711026

CarCheck.co.uk page 6/13



Tax & MOT check



X MOT

Tax expired: 3 June 2023

Expired: 11 January 2024

Tax status	Expired at 3 June 2023
Days left	332 days too late
MOT expiry date	11 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when mistery		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



71.777 mi

Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-05
Last registration	2023-01-04
Complete history	See info



Registration #1	2008-03-05	13 mi
Registration #2	2011-01-18	15.715 mi
Registration #3	2011-06-10	16.635 mi
Registration #4	2012-06-30	22.552 mi
Registration #5	2013-06-12	25.312 mi
Registration #6	2014-06-12	29.640 mi
Registration #7	2015-06-09	34.420 mi
Registration #8	2016-06-10	37.367 mi
Registration #9	2017-06-15	42.651 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

7070.70.70

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 13/13

Number of axles2Engine number8L44829