



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C200 CDI SPORT
Colour	Grey
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	270 Nm at 3.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





## MOT history

MOT expiry date	2023-05-17
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	27
Total items failed	7

MOT #15	2022-05-18 09:13
MOT test number	270612936596
Result	✓ Passed
Next expiry date	2023-05-17

MOT #14	2021-04-19 15:16
MOT test number	783673488860
Result	✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Engine undertray fitted
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13	2020-04-20 13:53
MOT test number	755603492908
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2020-04-20 13:53**MOT test number** 385466838355**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #11** 2019-04-19 13:48**MOT test number** 526386900490**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-04-16 15:52**MOT test number** 649646959350**Result** ✗ Failed**MAJOR** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-04-28 14:26**MOT test number** 988324184021**Result** ✓ Passed**MOT #8** 2018-04-28 10:24**MOT test number** 829262803752**Result** ✗ Failed**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #7** 2017-04-18 10:19**MOT test number** 854342901875**Result** ✓ Passed**MOT #6** 2016-04-30 16:04**MOT test number** 895443957518**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-04-13 15:47**MOT test number** 327313905106**Result** ✓ Passed**Notice** Stone chips in front screen**Notice** Items removed from driver's view prior to test

**MOT #4** 2015-04-13 12:31**MOT test number** 169783705172**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Notice** Stone chips in front screen**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Notice** Items removed from driver's view prior to test**Notice** N/s/f tyre wearing off on inner edge**MOT #3** 2014-04-09 16:20**MOT test number** 397199194093**Result** ✓ Passed**Notice** Stone chips in front screen.**MOT #2** 2013-04-30 16:22**MOT test number** 776080723163**Result** ✓ Passed**MOT #1** 2013-04-30 10:41**MOT test number** 495960423134**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

X

Untaxed

Tax expired:  
19 August 2022

X

MOT

Expired:  
17 May 2023

Tax status	Expired at 19 August 2022
Days left	620 days too late
MOT expiry date	17 May 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>FD59LLK</b>
Plate since	2019-03-29
Current registration	<b>FD59LLK</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-23
Last registration	2022-05-18
Complete history	<a href="#">See info</a>



Registration #1	2009-12-23	21 mi
Registration #2	2013-04-30	36.487 mi
Registration #3	2013-04-30	36.485 mi
Registration #4	2014-04-09	43.560 mi
Registration #5	2015-04-13	56.152 mi
Registration #6	2015-04-13	56.152 mi
Registration #7	2016-04-30	71.821 mi
Registration #8	2017-04-18	89.243 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi

More info >



Dimensions & weight

Width	2020 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	64681130387652