





General information

| Make | MAZDA |
|---------------------|----------------|
| Model | MX-5 I |
| Colour | Silver |
| Year of manufacture | 2004 |
| Top speed | 128 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 144 BHP |
|-------------------------|---------------------|
| Max. torque | 168 Nm at 5.000 rpm |
| Engine capacity | 1.839 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 24.8 mpg |
| Consumption extra urban | 39.8 mpg |
| Consumption combined | 32.5 mpg |
| CO2 emission | 210 g/km |
| CO2 label | К |







Internet history

Entry 1

Date

2021-05-22

6

Pictures

Listing price

View report



source: autotrader.co.uk





MOT history

| MOT expiry date | 2022-02-16 |
|--------------------|------------|
| MOT pass rate | 68 % |
| MOT passed | 15 |
| Failed MOT tests | 7 |
| Total advice items | 32 |
| Total items failed | 17 |

| MOT #22 | 2021-02-17 11:59 |
|------------------|------------------|
| MOT test number | 885940952240 |
| Result | ✓ Passed |
| Next expiry date | 2022-02-16 |

| MOT #21 | 2021-02-16 18:07 |
|---|------------------|
| MOT test number | 762342858382 |
| Result | 🗙 Failed |
| Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a)) | |

| MOT #20 | | 2020-02-13 13:22 |
|----------|--|------------------|
| MOT test | number | 994704706556 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii |)) |





| MOT #19 | 2020-01-28 15:55 |
|---|----------------------|
| MOT test number | 985339746662 |
| Result | 🗙 Failed |
| Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Fail Offside Rear Vehicle structure corroded to the extent that the rigidity of the assemble reduced (6.1.1 (c) (i)) | oly is significantly |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (| ii)) |
| Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the asser significantly reduced (6.1.1 (c) (i)) | nbly is |
| Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

MOT #182019-02-15 16:33MOT test number710869142398ResultPassedAdviceCracking to offside front tyreAdviceCracking to nearside rear tyreAdviceCracking to nearside rear tyreAdviceCracking to nearside front tyre

| MOT #17 | 2019-02-15 13:44 | |
|--|------------------|--|
| MOT test number | 120753590750 | |
| Result | 🗙 Failed | |
| Advice Cracking to nearside front tyre | | |
| Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) | | |
| Advice Cracking to offside front tyre | | |
| Advice Cracking to nearside rear tyre | | |





| MOT #16 | 2019-01-29 10:52 |
|--|------------------|
| MOT test number | 460664467188 |
| Result | 🗙 Failed |
| Fail Offside Rear Seat belt anchorage prescribed area strength or continuity significantly sill (7.1.1 (a) (i)) | reduced Outer |
| Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) | |
| Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |
| Advice Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive Outer sill (7.1.1 (a) (i)) | |
| Fail Brake pipe excessively corroded Front to rear (1.1.11 (c)) | |

| MOT #15 | | 2018-01-26 11:28 |
|----------|---|------------------|
| MOT test | number | 844789607421 |
| Result | | ✓ Passed |
| Advice | Brake pipe slightly corroded Front to rear (3.6.B.2c) | |
| Advice | Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | |

| MOT #14 | 2018-01-26 11:28 | |
|--|--|--|
| MOT test number | 583609733011 | |
| Result | × Failed | |
| Advice Brake pipe slightly corroded Front to rear (3.6.B.2c) | | |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) | |
| Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | | |
| Pass with rectification | Nearside Front position lamp(s) not working (1.1.A.3b) | |

| MOT #13 | 2017-01-27 10:43 |
|-----------------|------------------|
| MOT test number | 480569109680 |
| Result | ✓ Passed |





| NOT #12 | |
|--|------------------|
| MOT #12 | 2016-01-21 09:34 |
| MOT test number | 994080271118 |
| Result | ✓ Passed |
| MOT #11 | 2014-12-30 11:20 |
| MOT test number | 246124164383 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2014-01-28 11:23 |
| MOT test number | 148378024036 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2013-05-08 11:47 |
| MOT test number | 807898923174 |
| Result | ✓ Passed |
| Advice Brake pipe slightly corroded (3.6.B.2c) | |
| | |
| MOT #8 | 2012-05-16 09:11 |
| MOT test number | 755587732144 |
| Result | Passed |
| | |
| MOT #7 | 2011-05-23 12:35 |
| MOT test number | 685693441198 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2010-04-20 11:21 |
| | |
| MOT test number Result | 943280410120 |





| MOT #5 | | 2009-04-20 09:39 |
|----------|---|------------------|
| MOT test | number | 171950319152 |
| Result | | ✓ Passed |
| Notice | Front to rear brake pipe=Starting to corroded | |
| Notice | Near side front wheel bearing=Noisey (rotates freely and no play) | |
| Notice | Both rear tyres=Becoming perished (no canvas visable) | |
| Notice | Both front wipers=Smearing slightly | |
| Notice | Both rear brakes=Binding slightly | |
| Notice | Both rear brakes=Binding slightly | |

| МОТ #4 | 2009-04-17 17:35 |
|---|------------------|
| MOT test number | 292707209484 |
| Result | 🗙 Failed |
| Notice Near side front wheel bearing=Noisey (rotates freely and no play) | |
| Fail Nearside Front Headlamp aim too low (1.8) | |
| Notice Both rear tyres=Becoming perished (no canvas visable) | |
| Fail Brakes imbalanced across an axle (3.7.B.5b) | |
| Notice Both front wipers=Smearing slightly | |
| Notice Both rear brakes=Binding slightly | |
| Fail Offside Front Headlamp aim too low (1.8) | |
| Notice Front to rear brake pipe=Starting to corroded | |

| MOT #3 | 2008-06-05 15:56 |
|-----------------|------------------|
| MOT test number | 564207358196 |
| Result | ✓ Passed |





| 7258175 × Failed |
|---------------------|
| ✓ Failed |
| |
| |
| |
| |
| |
| |

| MOT #1 | 2007-05-29 10:00 |
|--|------------------|
| MOT test number | 692859347182 |
| Result | ✓ Passed |
| Advice Inner Front brake disc slightly pitted (3.5.1h) | |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------------|
| Date | FEIDO |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLI |
| Damage 2 | E E H - S - A |
| Date | * |
| Category | AMP. |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second s | |
|---|-------------|
| *********** | |
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| | |
| Current registration | |
| Current registration Plate since | |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 24 |
| First mileage registration | 2004-06-04 |
| Last registration | 2021-02-17 |
| Complete history | See info |



| Registration #1 | 2004-06-04 | 24 mi |
|--|------------|--|
| Registration #2 | 2007-05-29 | 12.559 mi |
| Registration #3 | 2008-06-05 | 15.390 mi |
| Registration #4 | 2008-06-05 | 15.394 mi |
| Registration #5 | 2009-04-17 | 17.329 mi |
| Registration #6 | 2009-04-20 | 17.329 mi |
| Registration #7 | 2010-04-20 | 29.581 mi |
| Registration #8 | 2011-05-23 | 44.634 mi |
| Registration #9 | 2012-05-16 | 47.875 mi |
| Registration #10 | 2013-05-08 | 51.946 mi |
| Registration #11 | 2014-01-28 | 54.257 mi |
| Registration #12 | 2014-12-30 | 55.085 mi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 esi |
| Registration #17 | | 11.777 mi |
| Registration #18 | | 11.777 esi |
| | | |
| Registration #19 | | 11.777 esi |
| Registration #19 Registration #20 | | 10.000 est |
| | | 10.000 est 10.000 est 10.000 est |
| Registration #20 | | 00.000 est 00.000 est 00.000 est 00.000 est |
| Registration #20 Registration #21 | | 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 |
| Registration #20 Registration #21 Registration #22 | | 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 |







Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1680 mm |
| Height | 1225 mm |
| Length | 3975 mm |
| Wheel base | 2265 mm |
| Kerb weight | 1065 kg |
| Max. allowed weight | 1305 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 50 I |
| | 50 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection |