



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO COMBI CDTI S/S
Colour	Silver
Year of manufacture	2016
Top speed	107 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 3

Date	2023-03-24
Pictures	16
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-07-04
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

Date	2021-06-16
Pictures	1
Listing price	View report



source: autoonline.co.uk

**MOT history**

MOT expiry date	2024-04-20
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	11
Total items failed	3

MOT #8	2023-04-21 17:04
MOT test number	219342453551
Result	✓ Passed
Next expiry date	2024-04-20

MOT #7	2023-04-21 09:11
MOT test number	238885076395
Result	✗ Failed
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #6	2022-07-23 09:28
MOT test number	760225841005
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2022-07-23 09:25
MOT test number	702709453452
Result	✗ Failed
Fail	Central Front Seat belt 'folded webbing' type load limiter deployed (7.1.3 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2021-07-22 08:31**MOT test number** 217713893957**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2021-07-20 11:27**MOT test number** 316901532499**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #2** 2020-11-20 16:16**MOT test number** 340179980153**Result** ✓ Passed**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2019-09-04 07:54**MOT test number** 451790216968**Result** ✓ Passed**Advice** NOTE: Unable to readily view all brakes for wear etc.**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
20 April 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	20 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VO66BVA
Plate since	2019-09-29
Current registration	 VO66BVA
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-09-01
Last registration	2023-04-21
Complete history	See info



Registration #1	2016-09-01	29 mi
Registration #2	2019-09-04	46.549 mi
Registration #3	2020-11-20	52.026 mi
Registration #4	2019-09-04	46.549 mi
Registration #5	2019-09-04	46.549 mi
Registration #6	2021-07-20	54.214 mi
Registration #7	2019-09-04	46.549 mi
Registration #8	2019-09-04	46.549 mi
Registration #9	2019-09-04	46.549 mi
Registration #10	2019-09-04	46.549 mi
Registration #11	2019-09-04	46.549 mi
Registration #12	2019-09-04	46.549 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1956 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1848 kg
Max. allowed weight	3020 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2
Engine number	R9M MH - C045111LQI