



Mercedes-Benz




report date: 2024-03-28

## General information

Make	MERCEDES
Model	C C180 KOMPRESSOR SPORT
Colour	Silver
Year of manufacture	2008
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	154 BHP
Max. torque	229 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	44.8 mpg
Consumption combined	34.9 mpg
CO2 emission	185 g/km
CO2 label	I



**MOT history**

<b>MOT expiry date</b>	2024-12-28
<b>MOT pass rate</b>	69 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	41
<b>Total items failed</b>	7

<b>MOT #16</b>	2023-12-04 12:33
<b>MOT test number</b>	876003252438
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-12-28
<b>Advice</b>	Nearside Front Suspension arm ball joint has slight play track control arm back one (5.3.4 (a) (i))
<b>Advice</b>	Rear sub frame corroded

<b>MOT #15</b>	2022-12-14 12:41
<b>MOT test number</b>	756398230498
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Minor</b>	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #14</b>	2021-12-29 14:39
<b>MOT test number</b>	820771189560
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front locking wheel nut damage

**MOT #13** 2021-12-29 11:27**MOT test number** 621158373914**Result** ✗ Failed**Fail** Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Offside Front locking wheel nut damage**MOT #12** 2020-09-22 09:00**MOT test number** 508460354016**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2020-09-21 15:03**MOT test number** 109607729922**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**MOT #10** 2019-02-27 07:37**MOT test number** 372118985639**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-02-25 16:44**MOT test number** 723474614790**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2018-02-07 16:14**MOT test number** 143498256392**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2017-02-20 15:00**MOT test number** 393578629378**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** O/s/f tyre worn inner edge and perished**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #6**

2017-02-20 15:00

**MOT test number**

690651111976

**Result****✗ Failed****Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** O/s/f tyre worn inner edge and perished**Pass with rectification** Body has a sharp edge caused by damage front bumper (6.1.C.1)**MOT #5**

2016-02-19 13:11

**MOT test number**

845409247146

**Result****✓ Passed****Advice** O/s/f tyre wearing on inner edge**Advice** Protective undertrays fitted**MOT #4**

2014-03-03 14:33

**MOT test number**

195482364080

**Result****✓ Passed****Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2012-03-20 11:07**MOT test number** 676070782018**Result** ✓ Passed**Notice** Off side front tyre and near side front tyre have had side wall repairs**Notice** Front tyres wearing on outer edges**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2012-03-20 11:07**MOT test number** 378240382003**Result** ✗ Failed**Notice** Front tyres wearing on outer edges**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Off side front tyre and near side front tyre have had side wall repairs**MOT #1** 2011-03-22 14:52**MOT test number** 617621581056**Result** ✓ Passed**Notice** Multiple undershields fitted restricting view



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
28 December 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	28 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 <b>DE08AXR</b>
Plate since	2019-09-29
Current registration	 <b>DE08AXR</b>
Plate since	2019-09-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-28
Last registration	2023-12-04
Complete history	<a href="#">See info</a>



Registration #1	2008-03-28	12 mi
Registration #2	2011-03-22	31.526 mi
Registration #3	2012-03-20	40.135 mi
Registration #4	2014-03-03	55.549 mi
Registration #5	2016-02-19	70.226 mi
Registration #6	2017-02-20	75.791 mi
Registration #7	2017-02-20	75.791 mi
Registration #8	2018-02-07	81.393 mi
Registration #9	2019-05-20	81.393 mi
Registration #10	2019-05-20	81.393 mi
Registration #11	2019-05-20	81.393 mi
Registration #12	2019-05-20	81.393 mi
Registration #13	2019-05-20	81.393 mi
Registration #14	2019-05-20	81.393 mi
Registration #15	2019-05-20	81.393 mi
Registration #16	2019-05-20	81.393 mi

More info >



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	27195231014212