





report date: 2024-03-29

### General information

Make	TOYOTA
Model	PREVIA VVT-I T SPIRIT 7STR
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	154 BHP
Max. torque	223 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	32.5 mpg
Consumption combined	26.2 mpg



CarCheck.co.uk page 1/11



## Internet history

### Entry 1

Date 2021-06-13

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



RV04HHJ

report date: 2024-03-29

#### **MOT** history

**MOT #17** 2021-10-05 10:38

MOT test number 723172280372

**Result** ✓ Passed

Next expiry date 2022-10-07

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge EDGE (5.2.3 (e))

Minor Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge EDGE (5.2.3 (e))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #16 2020-10-08 15:51

MOT test number 405925413898

**Result** 
✓ Passed

**MOT #15** 2019-09-21 13:14

MOT test number 995433098211

Result 

Passed

**MOT #14** 2018-09-21 13:33

**MOT test number** 826109375623

Result 

Very Passed

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

CarCheck.co.uk page 3/11



MOT #13 2018-09-21 13:33

**MOT test number** 570651773221

**Result** X Failed

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #12** 2017-08-10 15:04

**MOT test number** 414709537655

Result \( \sqrt{Passed} \)

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #11** 2016-08-31 15:40

MOT test number 180402060333

**MOT #10** 2015-09-01 16:03

MOT test number 127627357604

**Result** ✓ Passed

MOT #9 2014-08-30 13:37

**MOT test number** 109292844205

**Result** 
✓ Passed

MOT #8 2013-08-23 17:11

**MOT test number** 298235133213

**Result** ✓ Passed

CarCheck.co.uk page 4/11



RV04HHJ

report date: 2024-03-29

MOT #7		2013-08-23 17:11
MOT test number		889065833204
Result		<b>×</b> Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)	

MOT #6	2012-08-24 17:11
MOT test number	395397332453
Result	✓ Passed
MOT #5	2011-08-22 14:52
MOT test number	935054531234
Result	<b>✓</b> Passed
Advice Offside Front Shock absorber has a slightly reduced damping effect (2.7.5)	

MOT #4	2010-08-17 15:40
MOT test number	540819020221
Result	✓ Passed
MOT #3	2009-09-01 17:05
MOT test number	361534649483
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2	2008-09-03 16:24
MOT test number	372967748409
Result	<b>✓</b> Passed
MOT #1	2007-03-14 10:48
MOT test number	150303077444
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/11



RV04HHJ

report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this TOYOTA had different number plates.	
Number of plates	,
Correct registration	UK UK
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-03-17
Last registration	2021-10-05
Complete history	See info



Registration #1	2004-03-17	9 mi
Registration #2	2007-03-14	35.746 mi
Registration #3	2008-09-03	55.726 mi
Registration #4	2009-09-01	66.133 mi
Registration #5	2010-08-17	75.567 mi
Registration #6	2011-08-22	86.153 mi
Registration #7	2012-08-24	96.438 mi
Registration #8	2013-08-23	104.876 mi
Registration #9	2014-08-30	113.554 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		91,700 esi
Registration #18		11.777 au

More info >

page 10/11 CarCheck.co.uk



Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1790 mm
Height	1810 mm
Length	4750 mm
Wheel base	2900 mm
Kerb weight	1635 kg
Max. allowed weight	2355 kg

# Additional information

Fuel tank capacity	76 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles 2

Engine number 2AZB106344