





report date: 2024-03-29

### General information

Make	NISSAN
Model	350 Z V6
Colour	Black
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	276 BHP	
Max. torque	363 Nm at 4.800 rpm	
Engine capacity	3.498 сс	
Cylinders	6	
Fuel type	Petrol	
Consumption city	17.1 mpg	
Consumption extra urban	31.7 mpg	
Consumption combined	24.1 mpg	
CO2 emission	280 g/km	
CO2 label	М	



CarCheck.co.uk page 1/15



report date: 2024-03-29

## Internet history

### Entry 1

Date 2022-05-12

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

# MOT history

MOT expiry date	2025-04-24
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	27
Total items failed	9

MOT #23	2024-04-25 17:38
MOT test number	997813045275
Result	✓ Passed
Next expiry date	2025-04-24
Advice Nearside Front Brake pipe corroded, covered in grease or other materia	l (1.1.11 (c))

MOT #22	2024-03-16 09:16
MOT test number	264665791167
Result	🗙 Failed
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))	

CarCheck.co.uk page 3/15



Pass with rectification

SH05MKK

report date: 2024-03-29

**MOT #21** 2023-03-14 11:32 **MOT** test number 561633794138 ✓ Passed Result **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i)) Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i)) Advice **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

 MOT #20
 2022-03-08 10:11

 MOT test number
 861035415070

 Result
 ✓ Passed

 MOT #19
 2021-03-10 11:55

MOT test number 116969896177
Result ✓ Passed

MOT #18

MOT test number

943625075632

Result

Pass with rectification
(ii))

Nearside Front Suspension arm pin or bush likely to become detached (5.3.4 (a)

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #17

MOT test number

Result

2020-03-10 11:01

√ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #16** 2019-02-25 14:18

**MOT test number** 555231452163

**Result** ✓ Passed

MOT #15 2018-03-08 10:11

**MOT test number** 445417981872

Result 

Passed

**MOT #14** 2017-02-24 11:03

**MOT test number** 372548429899

Result \( \sqrt{Passed} \)

MOT #13 2016-03-09 14:33

**MOT test number** 764292923385

**MOT #12** 2016-03-05 11:36

**MOT test number** 515899597079

**Result** X Failed

**Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**MOT #11** 2015-03-07 10:18

**MOT test number** 979856365033

**Result** 
✓ Passed

**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/15



report date: 2024-03-29

**MOT #10** 2014-03-13 11:12

**MOT test number** 549712374035

**Result** 
✓ Passed

MOT #9 2013-03-15 15:17

**MOT test number** 395204573097

**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Nearside rear tyre worn on edge of tread

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2013-03-12 13:23

MOT test number 407511873020

**Result** X Failed

**Notice** Number plates deteriorated

**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Airbag light on

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Nearside rear tyre worn on edge of tread

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #7 2012-07-02 10:35
MOT test number 299294182493

Result \( \sqrt{Passed} \)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2011-06-27 15:05

MOT test number 299208271422

**Result** 
✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice BOTH FRONT TYRES WEARING INSIDE EGDE

MOT #5 2010-06-25 12:37

**MOT test number** 600886870128

**Result** ✓ Passed

MOT #4 2009-06-19 10:09

**MOT test number** 730860379184

**Result** ✓ Passed

MOT #3 2009-06-19 10:09

**MOT test number** 950730179142

Result X Failed

**Pass with rectification** Offside Headlamp aim too high (1.8)

**Pass with rectification** Nearside Headlamp aim too high (1.8)

MOT #2 2008-06-12 11:13

**MOT test number** 140504968133

Result 

Passed

CarCheck.co.uk page 7/15



SH05MKK report date: 2024-03-29

MOT #1 2008-06-10 10:16

**MOT test number** 102572568105

Result × Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 8/15



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	24 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



SH05MKK report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



faste since

SH05MKK

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this NISSAN had different number plates.

CarCheck.co.uk page 12/15



report date: 2024-03-29

### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-05-28
Last registration	2024-04-25
Complete history	See info



Registration #1	2005-05-28	24 mi
Registration #2	2008-06-10	12.237 mi
Registration #3	2008-06-12	12.253 mi
Registration #4	2009-06-19	15.811 mi
Registration #5	2010-06-25	19.753 mi
Registration #6	2011-06-27	23.963 mi
Registration #7	2012-07-02	27.621 mi
Registration #8	2013-03-12	30.848 mi
Registration #9	2013-03-15	30.850 mi
Registration #10	2014-03-13	31.724 mi
Registration #11	2015-03-07	32.816 mi
		22.127 :
Registration #12	2016-03-05	33.127 mi
Registration #12 Registration #13	2016-03-05	33.127 mi
Registration #13		
Registration #13 Registration #14		
Registration #13 Registration #14 Registration #15		
Registration #13 Registration #14 Registration #15 Registration #16		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		

More info >



SH05MKK report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

		_		
Dim	ension	<u>c                                    </u>	MOIO	ht.
וווט	CHSIOL	אט כו	weiu	I I L

Width	1815 mm
Height	1330 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1644 kg
Max. allowed weight	1820 kg

### Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	418568

CarCheck.co.uk page 15/15