



PEUGEOT

SA080NM


report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT TEPEE COMFORT L1 HDI 120 6STR
Colour	Black
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	44.8 mpg
Consumption combined	39.2 mpg



**MOT history**

MOT #12	2020-10-19 09:58
MOT test number	144547990616
Result	✓ Passed
Next expiry date	2021-10-24

MOT #11	2019-10-22 10:19
MOT test number	957254600101
Result	✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Fuel Tank Slightly Misted

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

Advice Meter No. - 12-00139

Advice Nearside Front Hub Nut Lock Pin Incorrect Device Fitted

MOT #10	2018-10-23 10:07
MOT test number	586411057003
Result	✓ Passed

MOT #9	2017-10-25 09:54
MOT test number	421310821802
Result	✓ Passed

Advice Front brake fluctuating, but not excessively (3.7.B.3)

MOT #8	2017-06-23 11:13
MOT test number	457373132735
Result	✓ Passed

Advice Nearside front cv boot deteriorated

**MOT #7** 2016-09-26 15:37**MOT test number** 990725976208**Result** ✓ Passed**MOT #6** 2015-06-20 10:35**MOT test number** 257171675139**Result** ✓ Passed**MOT #5** 2015-06-09 14:52**MOT test number** 715630265102**Result** ✗ Failed

Fail Offside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #4 2014-04-10 14:43**MOT test number** 855520204157**Result** ✓ Passed

Advice Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Notice Oil leak

MOT #3 2013-04-15 15:19**MOT test number** 677145503196**Result** ✓ Passed

Advice Offside Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Notice Passenger seat(s) missing at time of test



MOT #2	2012-10-16 13:45
MOT test number	319270192279
Result	✓ Passed

MOT #1	2009-03-18 17:50
MOT test number	293557779084
Result	✓ Passed
Notice	Front nearside and offside brake discs slightly worn
Notice	Front nearside mirror damaged



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-04-01
Last registration	2020-10-19
Complete history	See info



Registration #1	2008-04-01	24 mi
Registration #2	2009-03-18	43.988 mi
Registration #3	2012-10-16	136.759 mi
Registration #4	2013-04-15	151.012 mi
Registration #5	2014-04-10	175.228 mi
Registration #6	2015-06-09	204.639 mi
Registration #7	2015-06-20	204.648 mi
Registration #8	2016-06-20	204.648 mi
Registration #9	2016-06-20	204.648 mi
Registration #10	2016-06-20	204.648 mi
Registration #11	2016-06-20	204.648 mi
Registration #12	2016-06-20	204.648 mi
Registration #13	2016-06-20	204.648 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1998 mm
Height	1934 mm
Length	4806 mm
Wheel base	3000 mm
Kerb weight	1821 kg
Max. allowed weight	2759 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Engine number	DYWD4047991