





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	GLA GLA 220 D 4MATIC AMG LINE
Colour	White
Year of manufacture	2016
Top speed	135 mph
0 - 100 km/h	7.7 seconds
0 - 60 mph	7.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	130 kW / 177 HP / 174 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-22

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-10-24
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #7	2023-10-16 15:49
MOT test number	429869284808
Result	✓ Passed
Next expiry date	2024-10-24
Advice Under trays fitted covering components	

MOT #6		2022-10-20 13:32
MOT test	number	433752529893
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Nail in tyre	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2021-10-25 13:25
MOT test number	582745765618
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-10-14 14:42

MOT test number 358769788393

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Nearside Front Nail in tyre and wearing smooth outer edge

MOT #3 2020-11-16 10:36

MOT test number 342992733028

Result ✓ Passed

Advice Offside Front crack in tyre tread

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Nail in tyre

Advice Offside Rear crack in tyre tread

MOT #2 2020-11-16 10:36

MOT test number 405891895232

Result X Failed

Advice Offside Front crack in tyre tread

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear crack in tyre tread

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Nail in tyre

MOT #1 2019-05-20 14:11

MOT test number 918962189195

Result

Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

o which initially	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIK
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-05-31
Last registration	2023-10-16
Complete history	See info



Registration #1	2016-05-31	22 mi
Registration #2	2019-05-20	22.705 mi
Registration #3	2020-11-16	28.906 mi
Registration #4	2020-11-16	28.906 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



BT16VWK
report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1494 mm
Length	4417 mm
Wheel base	2699 mm
Kerb weight	1595 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	65193033688471