

Ford



General information

Make	FORD
Model	TRANSIT 300 SHR P/V
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP	0 < 101 A
ngine capacity	2.198 cc	101 - 120 ^B
linders	4	121 - 140 P
iel type	Diesel	141 - 165 F G
		100 105

225+



MOT history

MOT expiry date	2025-03-08
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	6
Total items failed	15

MOT #15	2024-02-09 13:33
MOT test number	953406995208
Result	✓ Passed
Next expiry date	2025-03-08

MOT #3	14	2024-02-09 09:07
MOT te	st number	519091892761
Result		🗙 Failed
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	

MOT #13		2023-02-10 14:09
MOT test	number	565771868759
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #12	2023-02-06 09:22
MOT test number	599339607155
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Rear Leaf spring main leaf fractured (5.3.1 (b) (ii))	

MOT #11	2022-02-14 14:15
MOT test number	655601860663
Result	✓ Passed

MOT #10	2022-02-14 10:33
MOT test number	678521617290
Result	🗙 Failed
Fail Nearside Rear Tyre has ply or cords exposed 195 70 15c (5.2.3 (d) (ii))	

MOT #9	2021-03-09 11:15
MOT test number	277406049373
Result	✓ Passed
Minor Nearside Front Outer Drive shaft joint constant velocity boot seve	erely deteriorated (6.1.7 (g) (i))





MOT #8		2021-03-08 14:51
MOT tes	t number	426042744731
Result		🗙 Failed
Fail	Horn not working (7.7 (a) (ii))	
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteri	orated (6.1.7 (g) (i))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4	7.1 (b) (ii))
Fail	Offside Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))	
Fail	Nearside Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))	
Fall	Nearside Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (l))	

MOT #7	2018-11-26 17:57
MOT test number	409597095497
Result	✓ Passed

МОТ #6	2018-11-26 15:26
MOT test number	802630802629
Result	× Failed

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #5	2017-11-24 12:55
MOT test number	584658126629
Result	✓ Passed
МОТ #4	2016-08-01 08:44
MOT test number	520684336797

Result	✓ Passed






MOT #3	}	2014-12-01 13:48
MOT te	st number	705485934382
Result		✓ Passed
MOT #2	2	2014-11-28 13:44
MOT te	st number	497182634479
Result		🗙 Failed
Fail	Offside Front wheel bearing has excessive play (2.5.A.3c)	
Fail	Offside Rear Shock absorber has a serious fluid leak (2.7.3)	
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #1	2013-12-05 09:05
MOT test number	737469733373
Result	✓ Passed



YC60NPN report date: 2024-03-29

Tax & MOT check







Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	
Category	 AMPL
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-16
Last registration	2024-02-09
Complete history	See info



Registration #1	2010-12-16	25 mi
Registration #2	2013-12-05	52.010 mi
Registration #3	2014-11-28	67.728 mi
Registration #4	2014-12-01	67.730 mi
Registration #5	2016-08-01	76.798 mi
Registration #6	2017-11-24	76.811 mi
Registration #7	2018-11-26	94.570 mi
Registration #8	2018-11-26	94.570 mi
Registration #9		
Registration #9 Registration #10		11.000 est
-		11.117 est 11.117 est
Registration #10		0.000 es
Registration #10 Registration #11		0.000 es
Registration #10 Registration #11 Registration #12		0.000 ee
Registration #10 Registration #11 Registration #12 Registration #13		0.000 ee 0.000 ee 0.000 ee 0.000 ee 0.000 ee 0.000 ee 0.000 ee

More info >





Car features

S0225	Air conditionin
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2374 mm
Length	5680 mm
Kerb weight	1876 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	AA84206