



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D SE
Colour	Orange
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg





Internet history

Entry 1

Date	2021-07-15
Pictures	20
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #15	2023-07-24 14:09
MOT test number	598439999889
Result	✓ Passed
Next expiry date	2024-07-25
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-07-22 11:34
MOT test number	435725283366
Result	✗ Failed
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #13	2022-06-27 09:58
MOT test number	672661911557
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-07-26 12:11
MOT test number	333444742428
Result	✓ Passed
Advice	General under body surface rust front to back on suspension components
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-07-16 10:52**MOT test number** 160002405800**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))**Advice** General under body surface rust front to back on suspension components**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2020-10-14 13:46**MOT test number** 649024850574**Result** ✓ Passed**MOT #9** 2020-10-12 09:01**MOT test number** 313219188187**Result** ✗ Failed**Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2019-04-26 14:09**MOT test number** 459805041042**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2018-04-25 11:56**MOT test number** 719806698758**Result** ✓ Passed

**MOT #6** 2017-04-12 12:43**MOT test number** 763990659686**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #5** 2016-04-25 12:58**MOT test number** 126676735652**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Both front tyres worn badly on inner edge, front wheel tracking needs adjusting ?**MOT #4** 2015-04-24 13:46**MOT test number** 909174215103**Result** ✓ Passed**MOT #3** 2014-04-28 12:27**MOT test number** 338448814177**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2014-04-24 14:07
MOT test number	916174114147
Result	✗ Failed
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-02-25 11:57
MOT test number	339716553042
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YD10JYX
Plate since	2019-03-29
Current registration	YD10JYX
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-01
Last registration	2023-07-24
Complete history	See info



Registration #1	2010-03-01	9 mi
Registration #2	2013-02-25	29.600 mi
Registration #3	2014-04-24	43.183 mi
Registration #4	2014-04-28	43.203 mi
Registration #5	2015-04-24	54.614 mi
Registration #6	2016-04-25	68.543 mi
Registration #7	2017-04-12	81.330 mi
Registration #8	2018-04-25	90.869 mi
Registration #9	2019-04-26	100.473 mi
Registration #10	2020-05-20	111.277 mi
Registration #11	2021-05-20	121.277 mi
Registration #12	2022-05-20	131.277 mi
Registration #13	2023-05-20	141.277 mi
Registration #14	2024-05-20	151.277 mi
Registration #15	2025-05-20	161.277 mi
Registration #16	2026-05-20	171.277 mi
Registration #17	2027-05-20	181.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1450 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	768432