



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT
Colour	Yellow
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-17
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	38
Total items failed	6

MOT #14	2024-04-18 13:45
MOT test number	995010839242
Result	✓ Passed
Next expiry date	2025-04-17
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-11-29 14:35
MOT test number	231334518930
Result	✓ Passed
Advice	Exhaust system/hangers corroded

MOT #12	2021-12-06 16:07
MOT test number	447728427911
Result	✓ Passed
Advice	Rear Exhaust mounting defective (6.1.2 (a))



MOT #11	2021-12-06 12:14
MOT test number	406541531111
Result	✗ Failed
MAJOR	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))

MOT #10	2020-12-07 16:33
MOT test number	999431259902
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Lhf of windscreen cracked lower corner

MOT #9	2020-12-04 17:14
MOT test number	794692009460
Result	✗ Failed
MAJOR	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Lhf of windscreen cracked lower corner
Advice	Rear wiper split
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Exhaust system insecure rear part of (6.1.2 (a))
Advice	Front pads low
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8**

2019-06-04 13:28

MOT test number

747440976277

Result

✓ Passed

Advice Oil leak, but not excessive on engine (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view chip in passenger side lower corner (3.2 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**MOT #7**

2019-06-04 10:32

MOT test number

690709662197

Result

✗ Failed

MAJOR Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Oil leak, but not excessive on engine (8.4.1 (a) (i))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6**

2018-06-06 14:57

MOT test number

731823540979

Result

✓ Passed

Advice Oil leaks but not excessive**Advice** Front wipers smearing**Advice** Both front tyres wearing on inner edges

**MOT #5** 2017-06-02 13:48**MOT test number** 615136581213**Result** ✓ Passed**Advice** Oil leaks**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-05-16 12:22**MOT test number** 938035034519**Result** ✓ Passed**Advice** Both front tyres worn on inner edges**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-05-16 11:56**MOT test number** 134815461924**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid front inop (8.2.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Both front tyres worn on inner edges**MOT #2** 2015-05-05 15:13**MOT test number** 975005825124**Result** ✓ Passed**Notice** Items removed from driver's view prior to test



MOT #12015-04-28 16:56

MOT test number775528515133

Result		✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice	Items removed from driver's view prior to test	
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
17 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	HW12KVE
Plate since	2019-09-28
Current registration	HW12KVE
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-05-02
Last registration	2024-04-18
Complete history	See info



Registration #1	2012-05-02	17 mi
Registration #2	2015-04-28	30.221 mi
Registration #3	2015-05-05	30.221 mi
Registration #4	2016-05-16	36.081 mi
Registration #5	2016-05-16	36.081 mi
Registration #6	2017-06-02	41.707 mi
Registration #7	2018-06-06	49.802 mi
Registration #8	2019-06-04	54.373 mi
Registration #9	2020-06-04	59.000 mi
Registration #10	2021-06-04	63.627 mi
Registration #11	2022-06-04	68.254 mi
Registration #12	2023-06-04	72.881 mi
Registration #13	2024-06-04	77.508 mi
Registration #14	2025-06-04	82.135 mi
Registration #15	2026-06-04	86.762 mi
Registration #16	2027-06-04	91.389 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEF3023664