



report date: 2024-03-29

General information

Make	FORD
Model	FUSION 16V ZETEC
Colour	Silver
Year of manufacture	2003
Top speed	104 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	158 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-17
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-01-31
MOT pass rate	59 %
MOT passed	16
Failed MOT tests	11
Total advice items	33
Total items failed	36

**MOT #27**

2022-02-09 17:02

MOT test number

933645745606

Result**✗ Failed**

- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect NO BEAM PATTERN (4.1.2 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Direction indicator incorrect colour SHOWING WHITE LIGHT (4.4.3 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Direction indicator incorrect colour SHOWING WHITE LIGHT (4.4.3 (a))

MOT #26

2021-01-25 17:01

MOT test number

930194207694

Result**✓ Passed**

**MOT #25** 2021-01-20 13:06**MOT test number** 641432082198**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #24** 2020-01-30 16:57**MOT test number** 432339758596**Result** ✓ Passed**MOT #23** 2019-02-01 16:20**MOT test number** 273596215688**Result** ✓ Passed**MOT #22** 2019-01-23 17:15**MOT test number** 334253403577**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

**MOT #21** 2019-01-16 16:36**MOT test number** 806054135352**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20 2019-01-07 11:30**MOT test number** 431942842025**Result** ✗ Failed

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #19 2017-11-23 14:47**MOT test number** 905106552243**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Front tyres are a not the correct size for the car



MOT #18	2016-10-21 15:31
MOT test number	891352535131
Result	✓ Passed
Advice	Rear rear brake fluctuating, but not excessively (3.7.B.3)

MOT #17	2016-10-10 16:31
MOT test number	675174799559
Result	✗ Failed
Advice	Rear rear brake fluctuating, but not excessively (3.7.B.3)
Fail	Offside Front Brake pipe excessively corroded (3.6.B.2c)
Fail	Offside Rear Brake pipe excessively corroded (3.6.B.2c)
Fail	Nearside Front Brake pipe excessively corroded (3.6.B.2c)
Fail	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

MOT #16	2015-11-04 10:40
MOT test number	605734826357
Result	✓ Passed
Advice	Brake pipe slightly corroded both rear (3.6.B.2c)
Advice	Oil leak

MOT #15	2014-11-05 13:47
MOT test number	489849104410
Result	✓ Passed



MOT #14	2014-11-05 12:11
MOT test number	635469104316
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #13	2013-11-08 11:50
MOT test number	437572313407
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Advise on faulty bonnet safety catch.
Notice	Advise on leaking gearbox diff seal.
Notice	Advise very slight rust on both rear brake pipes.
Notice	Advise front wiper rubbers starting to split.
Notice	Advise n/s/r tyre worn on the outer edge.

**MOT #12** 2013-11-06 14:24**MOT test number** 498610813327**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Notice** Advise on faulty bonnet safety catch.**Fail** Offside Front Headlamp aim too low (1.8)**Notice** Advise on leaking gearbox diff seal.**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Notice** Advise very slight rust on both rear brake pipes.**Fail** Nearside Front Headlamp aim too low (1.8)**Notice** Advise front wiper rubbers starting to split.**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Notice** Advise n/s/r tyre worn on the outer edge.**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #11** 2012-10-18 11:51**MOT test number** 105752292218**Result** ✓ Passed**MOT #10** 2011-11-07 15:20**MOT test number** 905061511349**Result** ✓ Passed

**MOT #9** 2011-11-03 10:52**MOT test number** 436527401482**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #8** 2010-11-04 15:20**MOT test number** 161148700345**Result** ✓ Passed**MOT #7** 2010-11-04 14:12**MOT test number** 891868600309**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #6** 2010-06-09 14:58**MOT test number** 811120960127**Result** ✓ Passed**MOT #5** 2009-06-19 14:41**MOT test number** 224450579196**Result** ✓ Passed**MOT #4** 2008-06-17 14:59**MOT test number** 583959768198**Result** ✓ Passed



MOT #3	2007-06-27 14:41
MOT test number	263958877160
Result	✓ Passed

MOT #2	2007-06-11 15:40
MOT test number	494032767156
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1	2006-06-13 17:14
MOT test number	551694766117
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
25 March 2022

X

MOT

Expired:
31 January 2022

Tax status	Expired at 25 March 2022
Days left	766 days too late
MOT expiry date	31 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2023-03-29
Current registration	XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2003-04-30
Last registration	2022-02-09
Complete history	See info



Registration #1	2003-04-30	14 mi
Registration #2	2006-06-13	11.392 mi
Registration #3	2007-06-11	13.803 mi
Registration #4	2007-06-27	13.936 mi
Registration #5	2008-06-17	16.671 mi
Registration #6	2009-06-19	19.025 mi
Registration #7	2010-06-09	21.745 mi
Registration #8	2010-11-04	22.630 mi
Registration #9	2010-11-04	22.639 mi
Registration #10	2011-11-03	29.304 mi
Registration #11	2011-11-07	29.304 mi
Registration #12	2012-10-18	36.150 mi
Registration #13	2013-11-06	47.916 mi
Registration #14	2013-11-08	47.976 mi
Registration #15	2014-11-05	61.124 mi
Registration #16	2015-05-20	75.277 mi
Registration #17	2015-05-20	75.277 mi
Registration #18	2015-05-20	75.277 mi
Registration #19	2015-05-20	75.277 mi
Registration #20	2015-05-20	75.277 mi
Registration #21	2015-05-20	75.277 mi
Registration #22	2015-05-20	75.277 mi
Registration #23	2015-05-20	75.277 mi
Registration #24	2015-05-20	75.277 mi
Registration #25	2015-05-20	75.277 mi
Registration #26	2015-05-20	75.277 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1463 mm
Length	3917 mm
Wheel base	2486 mm
Kerb weight	1076 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	3E55488