



report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Blue
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history


Entry 3

Date	2022-11-14
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2

Date	2022-11-10
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-18
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-01-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	32
Total items failed	0

MOT #13 2024-01-22 15:02**MOT test number** 942694601670**Result** Passed**Next expiry date** 2025-01-21**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #12** 2022-12-08 16:33**MOT test number** 824228317009**Result** Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2022-03-10 15:55

MOT test number

919662409257

Result

✓ Passed

Advice Front Coolant leak Radiator**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Front Prop shaft joint constant velocity boot severely deteriorated Ejecting grease (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2021-09-27 11:32

MOT test number

116489061495

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2020-09-28 07:10

MOT test number

978835077211

Result

✓ Passed

MOT #8

2020-09-23 13:29

MOT test number

934490474804

Result

✗ Failed

MAJOR Rear Exhaust silencer insecure (8.1.1 (b) (i))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #7** 2019-09-09 14:35**MOT test number** 906579020208**Result** ✓ Passed**MOT #6** 2018-09-20 10:36**MOT test number** 908330248038**Result** ✓ Passed**MOT #5** 2018-09-19 13:40**MOT test number** 357117055402**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))**MAJOR** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #4** 2017-09-21 16:39**MOT test number** 438340025087**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.2a)**Advice** Front tyres wearing inner edge**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.2a)**MOT #3** 2016-09-12 12:47**MOT test number** 104950679636**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)



MOT #2	2015-07-23 12:50
MOT test number	328074905228
Result	✓ Passed

MOT #1	2014-06-27 14:43
MOT test number	297018774184
Result	✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test
- Advice** Parking brake lever has little reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	EX11BVO
Plate since	2019-03-29
Current registration	EX11BVO
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-28
Last registration	2024-01-22
Complete history	See info



Registration #1	2011-06-28	15 mi
Registration #2	2014-06-27	22.494 mi
Registration #3	2015-07-23	29.496 mi
Registration #4	2016-09-12	40.910 mi
Registration #5	2017-09-21	48.896 mi
Registration #6	2018-09-19	58.211 mi
Registration #7	2018-09-20	58.270 mi
Registration #8	2019-09-09	69.272 mi
Registration #9	2020-09-23	76.667 mi
Registration #10	2020-09-23	76.667 mi
Registration #11	2020-09-23	76.667 mi
Registration #12	2020-09-23	76.667 mi
Registration #13	2020-09-23	76.667 mi
Registration #14	2020-09-23	76.667 mi
Registration #15	2020-09-23	76.667 mi
Registration #16	2020-09-23	76.667 mi
Registration #17	2020-09-23	76.667 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R210287355