



report date: 2024-03-28

General information

Make	CITROEN
Model	C3 HDI VTR PLUS PICASSO
Colour	Silver
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	312 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-04-07
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	20
Total items failed	16

MOT #12	2024-04-03 09:22
MOT test number	234014104106
Result	✓ Passed
Next expiry date	2025-04-07

MOT #11	2024-04-02 09:20
MOT test number	461352135903
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #10	2023-04-06 14:10
MOT test number	138564753170
Result	✓ Passed

**MOT #9** 2023-04-06 08:23**MOT test number** 260143061609**Result** ✗ Failed

- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Inner Brake disc in such a condition that it is seriously weakened face (1.1.14 (a) (ii))
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Inner Brake disc in such a condition that it is seriously weakened face (1.1.14 (a) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2022-04-04 11:05**MOT test number** 690316941407**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Rear suspension beam slightly corroded
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #7**

2022-04-04 11:05

**MOT test number**

285409990693

**Result**

✗ Failed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Rear suspension beam slightly corroded**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect Bulb incorrectly fitted (4.1.2 (c))**MOT #6**

2021-04-08 12:08

**MOT test number**

886050799495

**Result**

✓ Passed

**MOT #5**

2019-06-25 13:05

**MOT test number**

197777679127

**Result**

✓ Passed

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #4** 2019-06-25 11:56**MOT test number** 656558541838**Result** ✗ Failed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Front Exhaust system insecure (6.1.2 (a))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #3** 2018-05-08 14:09**MOT test number** 483769127636**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2018-05-08 14:09**MOT test number** 797790375589**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2017-05-23 15:54**MOT test number** 947216004016**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
7 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	7 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-11-30
Last registration	2024-04-03
Complete history	<a href="#">See info</a>



Registration #1	2014-11-30	12 mi
Registration #2	2017-05-23	1.698 mi
Registration #3	2018-05-08	19.050 mi
Registration #4	2018-05-08	19.050 mi
Registration #5	2019-06-25	39.066 mi
Registration #6	2019-06-25	39.066 mi
Registration #7	2019-06-25	39.066 mi
Registration #8	2019-06-25	39.066 mi
Registration #9	2019-06-25	39.066 mi
Registration #10	2019-06-25	39.066 mi
Registration #11	2019-06-25	39.066 mi
Registration #12	2019-06-25	39.066 mi
Registration #13	2019-06-25	39.066 mi
Registration #14	2019-06-25	39.066 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1404 kg
Max. allowed weight	1779 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFM0120939