



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC
Colour	Black
Year of manufacture	2017
Top speed	117 mph
0 - 100 km/h	15.9 seconds
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	63 kW / 86 HP / 123 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-10-16
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-05
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	3

MOT #7	2024-01-03 14:53
MOT test number	156112150352
Result	✓ Passed
Next expiry date	2025-01-05
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6	2022-12-15 13:49
MOT test number	364180914192
Result	✓ Passed

MOT #5	2022-01-06 09:38
MOT test number	627291292444
Result	✓ Passed

MOT #4	2021-09-22 11:16
MOT test number	817436770948
Result	✓ Passed

**MOT #3** 2020-12-15 15:14**MOT test number** 943733707436**Result** ✓ Passed**Advice** Nearside Front small chip/crack in windscreen**Advice** Offside Front door check strap broken**MOT #2** 2020-12-15 11:33**MOT test number** 922484602254**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Front Windscreen wiper does not clear the windscreen effectively both front (3.4 (b) (ii))**Advice** Nearside Front small chip/crack in windscreen**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Offside Front door check strap broken**MOT #1** 2020-01-21 12:01**MOT test number** 821234252403**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge sidewall also perished (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge sidewall also perished (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
5 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	5 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>MF17VVA</b>
Plate since	2019-03-28
Current registration	<b>MF17VVA</b>
Plate since	2019-03-28

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	9
First mileage registration	2017-03-13
Last registration	2024-01-03
Complete history	<a href="#">See info</a>



Registration #1	2017-03-13	16 mi
Registration #2	2020-01-21	53.570 mi
Registration #3	2020-12-15	64.738 mi
Registration #4	2020-12-15	64.738 mi
Registration #5	2021-09-22	66.931 mi
Registration #6	2022-05-20	68.277 mi
Registration #7	2022-05-20	68.277 mi
Registration #8	2022-05-20	68.277 mi
Registration #9	2024-01-03	70.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2067 mm
Height	1610 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1374 kg
Max. allowed weight	1860 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	HC76855
---------------	---------