



report date: 2024-03-28

General information

Make	NISSAN
Model	LEAF TEKNA
Colour	Silver
Year of manufacture	2015
Top speed	87 mph
0 - 60 mph	11.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-10-10
Pictures	20
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-09
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-19
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	21
Total items failed	5

MOT #9	2023-06-22 12:43
MOT test number	169439201708
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #8	2023-06-22 09:41
MOT test number	450865875286
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #7**

2022-07-01 13:11

**MOT test number**

939304775513

**Result**

✓ Passed

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge low on edges (5.2.3 (e))

**MOT #6**

2022-07-01 09:13

**MOT test number**

874571434100

**Result**

✗ Failed

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge low on edges (5.2.3 (e))

**Fail**

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail**

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice**

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge low on edges (5.2.3 (e))

**Fail**

Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #5**

2021-07-16 14:01

**MOT test number**

602036076314

**Result**

✓ Passed

**Advice**

Nearside Front tyre worn on inner and outer edges..cuts in tyre (not to cords)

**Advice**

Front both front wishbone bushes cracked and perished(not excessive)

**Advice**

Offside Front worn on inner and outer edges



<b>MOT #4</b>	2020-07-20 13:41
---------------	------------------

<b>MOT test number</b>	331664328936
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2020-07-20 10:48
---------------	------------------

<b>MOT test number</b>	231711130816
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
-------------	--

<b>MOT #2</b>	2019-05-08 16:04
---------------	------------------

<b>MOT test number</b>	990702884931
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	---

<b>MOT #1</b>	2018-05-03 08:50
---------------	------------------

<b>MOT test number</b>	365714536732
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 April 2025

✓  
**MOT**

**Expires:**  
19 July 2024

Tax status		Valid until 1 April
Days left		338
MOT expiry date		19 July 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-11
Last registration	2023-06-22
Complete history	<a href="#">See info</a>



Registration #1	2015-05-11	25 mi
Registration #2	2018-05-03	22.135 mi
Registration #3	2019-05-08	31.173 mi
Registration #4	2020-07-20	39.634 mi
Registration #5	2020-07-20	39.634 mi
Registration #6	2021-07-16	46.381 mi
Registration #7	2023-06-22	55.277 mi
Registration #8	2023-06-22	55.277 mi
Registration #9	2023-06-22	55.277 mi
Registration #10	2023-06-22	55.277 mi
Registration #11	2023-06-22	55.277 mi
Registration #12	2023-06-22	55.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1525 kg
Max. allowed weight	1945 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	078294A
---------------	---------